GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
December 16, 2013

Reviewed: _____

Mine Name: Lone Pine Quarry	**Permit Number**: M/003/0050
Operator Name: Gold Star Stone, Inc	**Inspection Date**: June 5, 2013
Inspector(s): Lynn Kunzler and Steve Schneider	**Time**: 10:30 am
Other Participants: None	**Mine Status**: inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	☒	☒	☐
2. Public Safety (shafts, adits, trash, signs, highwalls)	☒	☒	☐
3. Protection of Drainages / Erosion Control	☐	☐	☐
4. Deleterious Material	☐	☐	☐
5. Roads (maintenance, surfacing, dust control, safety)	☐	☐	☐
6. Concurrent Reclamation	☐	☐	☐
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	☒	☒	☐
8. Soils	☐	☐	☐
9. Revegetation	☐	☐	☐
10. Other	☐	☐	☐

Purpose of Inspection:
Routine Inspection.

Inspection Summary:
The annual permit fee has been paid. The Division currently holds a reclamation surety (CD) of $48,900 which is due for escalation in August of 2015.

There was no mining activity at this site. Likewise no equipment or materials for quarrying or palleting stone. There were two camp trailers on site, one has been flattened by apparent winter storms. While activity was reported for last year, a large portion of the area has had no activity, based on the amount of volunteer vegetation that has established.

Aside from the mess of this trailer, the area was free of garbage and debris. The site was also stable with no apparent erosion problems.

Photos were taken to document site conditions

Conclusions and Recommendations:
The operator needs to clean up the debris from the destroyed trailer and properly dispose of this material.

Inspector's Signature _____

cc: Barry Peterson, Operator
O:\M003-BoxElder\M0030050-LonePine\inspections\Insp-06052013.doc