3/27 LK

N

FORM MR-AR
(Revised 12/93)

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

RECEIVED
JAN 30 1995
DIV OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) 1-94 To (mo./yr.) 1-95
2. DOGM File Number (Mine No): S /003027
3. Mine Name: FISHER CREEK
4. Mineral(s) Mined (or permitted to mine): QUARTZITE FLAGSTONE
5. Type of mine ☑ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
   ____1/4, ____1/4, Section 8, Township 13N., Range 13W.
   ____1/4, ____1/4, Section ____, Township ____, Range ____
   ____1/4, ____1/4, Section ____, Township ____, Range ____
7. Name of Operator or Company: WILLIAM L BOWN
8. Permanent Street Address : 842 W 400 No
   City, State, Zip: WEST BOUNTIFUL, UTAH 84087
   Phone: 801-295-0601
9. Company Representative (or designated operator):
   Name: ____
   Title: ____
   Business Address: ____
   City, State, Zip: ____
   Phone: ____

☐ Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☑ No ☐
2. If active, how much ore or mineral was mined? 300 TONS

3. How much additional acreage was disturbed during the past year? NONE

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

TOTAL TONNAGE WAS REMOVED FROM QUARRY WALL (EXISTING) AND SPILL-WAY NO NEW DISTURBANCE OF ACREAGE

5. How much acreage was reclaimed during the past year? NONE

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

NONE

7. What is the total disturbed acreage at years end? 3.5

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

PLANS ARE TO RECLAIM ACCESS ROUTE ON WEST SIDE OF CANYON, AND CONSTRUCTION OF NEW ACCESS ON SAME. ACTUATION OF DRAG-LINE AND FURTHER REMOVAL OF STONE FROM EAST QUARRY AND SPILL-WAY (WASTE) PILE

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.

2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): WILLIAM L BOWN

Title of Operator: OWNER

Signature of Operator: William L Bown

Date: 18 JAN. '95

jb