M/015/061

DOGM
5/20/96

A. Bentonite stockpile in the center of Western Clay Company's mine, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.

B. Iron scrap located at the eastern edge of the mine, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.

M/015/061

DOGM
5/20/96

C. Southwest part of the bentonite mine, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.

D. Northwest portion of the bentonite mine, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.

M/015/061
DOGM
5/20/96

G. Closeup of the upper part of the hill access road, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.

H. Top of hill stripped of overburden, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 7/8. 5-2-96.

M/015/061

DOGM
5/20/96

I. Looking southeast over the top of the hill, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.

J. Spillage on the north side of the top of the hill, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.

M/015/061

DOGM
5/20/96

K. Bulldozer access trail coming up the north side of the hill, Western Clay Company, notice UTU-69862, in T.25S., R.6E., Section 8. 5-2-96.

L. Bulldozer access trail on the north side of the pit, Western Clay Company, notice UTU-69862 in T.25S., R.6E., Section 8. 5-2-96.