5/015/046

A. Blocked-off access road, Tom Clark, Notice UTU-69856 in T.22S., R.6E., Section 26. 5-9-97.

B. Tracks going around the barrier on the old access road, Tom Clark, Notice UTU-69856 in T.22S., R.6E., Section 26. 5-9-97.

5/015/046

C. New electric control panel just east of the generator, Tom Clark, Notice UTU-69856 in T22S., R.6E., Section 26. 5-9-97.

D. Portapotty located just north of the portals, Tom Clark, Notice UTU-69856 in T.22S., R.6E., Section 26. 5-9-97.

5/015/046

E. Stockpile located on the old access road north of the nortals, Tom Clark, Notice UTU-69856 in T.22S., R.6E., Section 26. 5-9-97.

F. Disturbed area on the north side of the operation, Tom Clark, Notice UTU-69856 in T.22S., R.6E., Section 26. 5-9-97.

5/015/046

G. Fuel tanks on the western edge of the operation just north of the access road, Tom Clark, Notice UTU-69856 in T.22S., R.6E., Section 26. 5-9-97.

H. Stockpiles in the truck turnaround area north of the fuel tanks, Tom Clark, Notice UTU-69856 in T.22S., R.6E., Section 26. 5-9-97.