FORM MR-AR
(Revised 2/2001)

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

2003 ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. *General Information*

1. Report Time Period: From (mo./yr.) 01/03 To (mo./yr.) 01/04
2. DOGM File Number (Mine No): S/150/090
3. Mine Name: The Rockland Mine
4. Mineral(s) Mined (or permitted to mine): Shale/Clay
5. Type of mine ☐ Surface Mine or ☒ Underground Mine
6. Legal Description (Location of Lands Affected):
   ____1/4, SE 1/4, SW 1/4, Section 2+3, Township 23 South, Range 6 East
   ____1/4, ____1/4, ____1/4, Section 34, Township 22 South, Range 6 East
   ____1/4, ____1/4, ____1/4, Section ____, Township ____, Range ____
7. Name of Operator or Company: The Rockland Corporation
8. Permanent Street Address: 12320 E. Skelly Drive
   City, State, Zip: Tulsa, OK 74128
   Phone: 918-437-7310 Fax: 918-492-9546
9. Company Representative (or designated operator):
   Name: Rocky Heinrich
   Title: President
   Business Address: 400 South 100 East
   City, State, Zip: Emery, Utah 84522
   Phone: 435-286-2460 Fax: 435-286-2471

☐ **Please check if any of the above information has changed since previous year.**

II. *Mining and Reclamation*

1. Was there any mine related activity during the past year? Yes ☒ No ☐
2. If no - what was the last year of activity? ____
3. If yes - how much ore or mineral was mined? —5,235 tons—

Reviewed 3/1/04

RECEIVED
JAN 26 2004
DIV. OF OIL, GAS & MINING

4. Briefly describe the type of work performed, volume of material moved, and any new or additional surface disturbances that occurred during the past year.

Humic shale clay is removed via underground mining. No surface disturbances have occurred during the past year.

5. How much **additional acreage** was disturbed during the past year? NONE

6. How much acreage was **reclaimed** during the past year? NONE

7. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

NONE

8. What is the **total disturbed acreage of entire project** at years end? Ø

9. Briefly summarize any mining and/or reclamation plans for the upcoming year.

Mining will continue ... no other plans.

NOTE: Section III., "Additional Information" applies only to **large mining operations.**

III. *Additional Information - R647-4-121.2 and .3*

1. **The operator shall include an updated map depicting surface disturbance and reclamation performed during the year**, prepared in accordance with Rule R647-4-105.

2. The operator shall keep and maintain timely records relating to his performance under the Act, and shall make these records available to the Division upon request.

IV. *Signature Requirement*

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Rocky Heinrich

Title of Operator: President - The Rockland Corporation

Signature of Operator: Rocky Heinrich

Date: 1-20-04

jb
o:\forms\reports\MR-AR