

8/18/76

View down Shitemaring Canyon over the tailings dam. Evidence of bentonite (rolled) in bottom & scattered bent. on dam. Dam does not appear adequately sealed.

D603031 P

8/18/76

Drainage into tailings pond. View to the east over dam at water notch in cliff. All drainage over this notch appears to drain into tailings pond.

D603031 P