ACCURACY JE[illegible]L LEGAL PAD No. 59-6670 8½ IN. x [illegible]4 IN. · 50 SHEETS THE MEAD[illegible]RPORATION, DAYTON, O. 45402

Comments on Natural Resources

→ Will any temporary seeding be done on dam face?
- No deep rooted species should be allowed.

→ Map showing topsoil stockpile is notified to anything cannot locate in relation to pond site.

→ Where is bore site shown in figure 8 in relation to pond site? (Dewatering Study)

→ Water Rights stips on construction need to be reinforced. Serious problem may exist from possible piping.

→ How about the site location in relation to other mining operations (are any under site?).

Route to:

Wayne/Tom
Joe
Margann

For comment -

Stability analysis looks good - reclamation plan ~~[illegible]~~. will be submitted (hopefully) this week (by 9/12/80) - I hope to write executive summary for Board ~~Mon~~ Friday Sept 19, or Monday Sept. 22.

Lee.

9/11/80 Note: Several items were delivered by Karen Jackson. They are stamped. I told her we wanted: (1) A map which defines and ~~ts~~ labels the ~~area at~~ land affected.

(2) Legal subdivision (sec, twp, rng.) shown on the map.

9/11 X (3) A letter stating that the amendment is ~~a~~ requested to the Tony M. mine plan.

9/18 map X (4) Full disclosure on the map of all facilities, ie. the water tank, water lines, and facilities. these appear to be a separate consideration.

Lee

9-3-80

Route to Lee, Wayne & (Tom for reclamation plans, Mary Ann, Joe) for review and comment.

Lee,

Would you please take primary responsibility? The mine has been approved, but they've run into more water than anticipated and now want to modify their impoundment from 1.67 acres to 17 acres (total containment and evaporation) I believe they have been to Dam Safety, but I'm not sure about Water Quality. I told them we may have to republish due to being a "major" modification and the surety amount would more than likely be readjusted (I think it's a contract). Also, they are lacking reclamation information and a revised surface facilities map showing new location of impoundment. This information & a letter of introduction for the modification is forthcoming. Thanks.

Mary Ann did all the work on Tony M. previously.

Comments on Plateau Resources

ok → Will any temporary seeding be done on dam face?
- No deep rooted species should be allowed.

ok → Map showing topsoil stockpile is not tied to anything
no/ can not locate in relation to pond site.

? → Where is bore site shown in figure 8 in relation to pond site? (Dewatering Study)

ok → Water Rights stips on construction need to be reinforced. Serious problem may exist from possible piping.

ok → How about the site location in relation to other mining operations (are any under site?).

---

ok → Will there be a spillway or overflow? or will it be total Containment.

ok → How about watershed above pond? Has pond been sized to handle flow from mine and natural Runoff

LS
9/24/80