Section 32 (state)
Impoundment (reconstructed since 1995 blowout)
(upper?)

Million $ Gulch disturbances
just upstream from the processing
ponds
E → W view

Assorted processing
equipment

Million $ Gulch
lower extent of disturbance
bottom end of drainage

Water surge/storage tank (now inactive + bypassed)

Lower end of existing (newer) disturbance Million Dollar Gulch processing area

Storage tank (now bypassed) + new water supply line
(surge?)

Million $ Gulch (on ridge line (North side) just above processing site

Million $ Gulch
ponds
looking down-drainage
W → E

Million $ Gulch processing
equipment & reconstructed
process
ponds

updrainage
East to West view

Million Dollar Gulch
new constructed (rebuilt) ponds

updrainage view
E → W