JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
October 7, 2008

Reviewed PBB

Mine Name: Rhae-Rae	**Permit Number**: S019/0064
Operator Name: Black Gold Organic Fertilizer	**Inspection Date**: July 29, 2008
Inspector(s): T Munson	**Time**: 2:00 PM - 2:30 PM
Other Participants: None	**Mine Status**: Inactive

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	☐	☐	☐
2. Public Safety (shafts, adits, trash, signs, highwalls)	☒	☒	☒
3. Protection of Drainages / Erosion Control	☐	☐	☐
4. Deleterious Material	☐	☐	☐
5. Roads (maintenance, surfacing, dust control, safety)	☐	☐	☐
6. Reclamation	☐	☐	☐
7. Backfilling/Grading (trenches, pits, roads, highwalls,	☐	☐	☐
8. Soils	☐	☐	☐
9. Revegetation	☐	☐	☐

Bond Renewal Date: 11/16/2010 **Bond Amount:** $20,700 **Permit fee** delinquent

Purpose of Inspection: To verify that the barrels of potentially hazardous waste had been removed from the site based on the issuance of cessation order # MC-2008-25-01.

Inspection Summary: The operator contacted me on July 16, 2008 to inform me that the barrels had been removed and I could perform my inspection. I arrived onsite on July 29, 2008 and photo documented that the barrels had been removed. The cessation order can now be terminated.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator still has oil and grease on site in an open containment that should be emptied and other oil and grease buckets that exist on site should be put in proper containers so spills do not occur. OGM to continue annual inspections and monitor the site when in the area. A call will be made to the operator to request permit fees.

Inspector's Signature Thomas Munson

TM:pb
cc: (OPERATOR)
wstokes @utah.gov
O:\M019-Grand\S0190064-RheaRae\inspections\insp-07292008.doc

0006

S0190064 - Black Gold Organic Fertilizer
Photos taken 07/29/2008

Hazardous waste barrels removed from site

Barrels removed from embankment of pond

Oil waste contained in metal tray. This tray needs to be cleaned before it becomes a problem.

Other bags of materials are found on site and although they are considered nonhazradous they should be stored out of the weather before they become unusable and spill on the ground.