JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
Report Date: April 3, 2007

Supervisor DRH

Mine Name: Highland Mist
Operator Name: Anasazi Gold Reserves
Michael Terry
C/O North American Exploration
447 North 300 West Suite 3
Kaysville, Utah 84037-4203
Inspector(s): Doug Jensen, Daron Haddock
Other Participants: None
Mine Status: Inactive

Permit number: S/021/035
Inspection Date: February 12, 2007
Time: 11:00 AM

Weather: Clear, warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	☐	☐	☐
2. Public Safety (shafts, adits, trash, signs, highwalls)	☐	☐	☐
3. Protection of Drainages / Erosion Control	☐	☐	☐
4. Deleterious Material	☒	☐	☐
5. Roads (maintenance, surfacing, dust control, safety)	☐	☐	☐
6. Concurrent Reclamation	☐	☐	☐
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	☐	☐	☐
8. Water Impoundments	☐	☐	☐
9. Soils	☐	☐	☐
10. Revegetation	☐	☐	☐
11. Air Quality	☐	☐	☐
12. Other	☒	☒	☐

Purpose of Inspection:
Inspected this site while in the area.

Directions to Site:
The site is located immediately off highway 20 (approximately 10 miles from freeway), southeast of Beaver.

Inspection Summary:
There has been some recent activity at the site. The stockpile of material has been removed from the site. No one was at the site. The site is fairly stable and no concerns were noted..
No photos or GPS data was collected during this inspection.

Conclusions and Recommendations:
Need to review annual report to see if the production was recorded.

Inspector's Signature Daron R. Haddock **Date:** 4/3/07

dh:pb
cc: North American Exploration
Will Stoke, SITLA ML-49111
P:\GROUPS\MINERALS\WP\M021-Iron\S0210035-HighlandMist\inspections\02122007insp.doc