FORM MR-AR
(Revised 12/93)

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
Telephone: (801) 538-5340
Fax: (801) 359-3940

RECEIVED
JAN 29 1996
DIV OF OIL, GAS & MINING

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

1. Report Time Period: From (mo./yr.) Jan 1995 To (mo./yr.) Dec 1995
2. DOGM File Number (Mine No): M /023 /023
3. Mine Name: Henry # 1 and # 2 Mine
4. Mineral(s) Mined (or permitted to mine): Gypsum
5. Type of mine ☒ Surface Mine or ☐ Underground Mine
6. Legal Description (Location of Lands Affected):
   SE 1/4, NW 1/4, Section 19, Township 15 S, Range 1 E
   W½ 1/4, NE 1/4, Section 19, Township 15 S, Range 1 E
   NW 1/4, SE 1/4, Section 19, Township 15 S, Range 1 E
7. Name of Operator or Company: H. E. Davis & Sons
8. Permanent Street Address : 525 West Arrowhead Trail
   City, State, Zip: Spanish Fork, Utah 84660
   Phone: (801) 798 - 7355
9. Company Representative (or designated operator):
   Name: Harold E. Davis
   Title: President
   Business Address: 525 West Arrowhead Trail
   City, State, Zip: Spanish Fork, Utah 84660
   Phone: (801) 798 - 7355

☐ **Please check if any of the above information has changed since previous year.**

II. Mining and Reclamation

1. Was the mine active during the past year? Yes ☒ No ☐
2. If active, how much ore or mineral was mined? 19,954

3. How much **additional acreage** was disturbed during the past year? **NONE**

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

NONE

5. How much acreage was **reclaimed** during the past year? **LESS THAN 1/10 ACRE**

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

A new bench was formed on the east side of the mine area with topsoil being placed and re-seeding completed.

7. What is the **total disturbed acreage** at years end? **7.92 ACRES**

8. Briefly summarize any mining and/or reclamation plans for the upcoming year.

We have purchased five (5) acres to the west of the tailings pile for the purpose of additional tailings storage if necessary.

NOTE: Section III., "Additional Information" applies only to **large mining operations**.

III. Additional Information

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted.

2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached.

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): H. E. Davis & Sons

Title of Operator: President Harold E Davis

Signature of Operator:

Date: January 26, 1996

jb