GARY R. HERBERT
Governor
GREGORY S. BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
August 23, 2012

Reviewed: PBB

Mine Name: Treasure Chest	**Permit Number**: S/023/0028
Operator Name: The Bug House	**Inspection Date**: ~~October 26, 2011~~ 8/23/2012
Inspector(s): Wayne Western	**Time**: 1:00 – 1:30 pm
Other Participants: none	**Mine Status**: Suspended
Weather Condition: 81 degrees partly cloudy	**Last Inspection**: June 30, 2010
Bond Renewal Date: April 5, 2014	**Bond Amount**: $11,900
Surface Ownership: BLM	**Mineral Ownership**: BLM
Last Year of Production: 2011	**Acreage**: 1 acres

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer,	☒	☐	☐
2. Bond/Bond Release	☒	☐	☐
3. Annual Fees	☒	☐	☐
4. Annual Report	☒	☐	☐
5. Public Safety (shafts, adits, trash, signs, highwalls)	☐	☐	☐
6. Protection of Drainages / Erosion Control	☐	☐	☐
7. Deleterious Material	☐	☐	☐
8. Roads (maintenance, surfacing, dust control, safety)	☐	☐	☐
9. Concurrent Reclamation	☐	☐	☐
10. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	☐	☐	☐
11. Water Impoundments	☐	☐	☐
12. Soils	☐	☐	☐
13. Re-vegetation	☐	☐	☐
14. Air Quality	☐	☐	☐
15. Other			

Purpose of Inspection:

This is a routine inspection.

Inspection Summary:

The Operator is making payments on the bond. By December 31, 2012 they show post an additional $2,900.00 to bring the bond to a total of $11,900.00.

The site use to be used by rockhounds. The Operator has since closed the site to the public and place signs around the pit.

The site has no equipment on site. The site appears to be stable.

Conclusions and Recommendations:

The Division monitor the site and bond.

Directions to Site:

Inspector's Signature Wayne Walton

WHW:
cc: (OPERATOR)
Jerry Mansfield, BLM
O:\M023-Juab\S0230028-treasurechest\inspections\Insp-08232012.doc

The area has been closed to the public.

No trespassing signs have been posted at both entrances

Disturbed area

Processing equipment