Leslie

Rio Tinto

Barneys Canyon Mining Company
P.O. Box 3111
Bingham Canyon, Utah 84006
USA
T 801-569-7110

Phil Lehoux
Acting Operations Manager
Barneys Canyon Mine

RECEIVED E-Mail
FEB 03 2014
Div. of Oil, Gas & Mining

Mr. Paul Baker, Minerals Program Manager
Division of Oil, Gas & Mining
Utah Department of Natural Resources
1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801

January 31, 2014

Attn: Ms. Leslie Heppler

Re: Large Mining Operations 2011 Progress Report
January 1, 2013 to December 31, 2013
M/035/0009
Barneys Canyon Mine

Dear Mr. Baker:

Please find attached Form MR-AR for permit number M/035/0009, Barneys Canyon Mine.

If you have any questions about these annual reports, please contact me at 801.569.7110.

Sincerely,

Phil Lehoux

C: Dana Dean (UDOGM)

FORM MR-AR
(Revised 11/2008)

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING
1594 West North Temple - Suite 1210
Box 145801
Salt Lake City, Utah 84114-5801
Telephone: (801) 538-5291
Fax: (801) 359-3940

LARGE MINING OPERATIONS 2013 PROGRESS REPORT

January 1, 2013 to December 31, 2013

The information required in this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, and the rules as under the Utah Minerals Regulatory Program.

1. Mine Permit Number: *M/035/0009*
2. Mine Name: *Barneys Canyon*
3. Name of Operator/Permittee: *Kennecott Utah Copper LLC (KUC) Barneys Canyon Mine*

Note: If Operator's address, company representative or phone number have changed, please provide a replacement page for the Notice of Intention.

4. Mine Location:
S1/2 SW1/4, Section 17;
N1/2 NW1/4, W1/2 NE1/4, SE1/4 NE1/4, E1/2 SE1/4 Section 20;
SW1/4 SW1/4, Section 21;
W1/4 NW1/4, Section 28;
NE1/4 NE1/4, Section 29;
Township 3 South, Range 3 West

5. Report the gross amount of ore mined and waste moved, and the disposition of the materials (onsite stockpiles, sold, waste pile, regraded, etc.):

Gross Ore Mined	0	Tons
Waste Material Moved	0	Tons
New Disturbance	0	Acres during 2013
Area Reclaimed	0	Acres during 2013
Total Disturbed Area	306	Acres*

*Total mine disturbance from the beginning of mining operations through the end of 2013.

Was the ore shipped off site? If not, where is the ore located?

No ore was generated in 2013, however 14,582 tons of sulfide stockpile material was shipped off site for processing.

Where is the waste located?

All waste (i.e. waste rock) is located on site.

6. Briefly describe the reclamation work performed during the past year. A map showing reclaimed areas and dates is suggested. (Submit form MR-SITE for an application for full or partial bond/site release).

No reclamation work was performed during the past year. Primarily the disturbed acreage remaining at Barneys Canyon includes the five heap leach pads, leach solution ponds, ore processing building and sulfide ore stockpile.

7. **Include an updated map depicting surface disturbance and reclamation performed during the year**, prepared in accordance with Rule R647-4-105.

No new surface disturbances or reclamation was performed in 2013.

I hereby certify, under penalties of law, the information provided in this report is true and correct to the best of my knowledge and belief.

Name (Typed or Print): *Phil LeHoux*

Title of Operator: Acting *Operations Manager*

Signature of Operator: _____

Date: ***January 31, 2014***

pb

O:\FORMS\reports\MR-AR-LMO2008.doc