M/045/017

BARRICK

BARRICK RESOURCES (USA), INC.

July 30, 1990

DOGM
MINERALS PROGRAM
FILE COPY

RECEIVED
AUG 01 1990
DIVISION OF
OIL, GAS & MINING

Mr. Donald A. Ostler, P.E.
Executive Secretary
Utah Water Pollution Control Committee
P.O. box 16690
Salt Lake City, Utah 84116-0690

Dear Mr. Ostler:

Subject: Groundwater Quality Discharge Permit No. UGW450001

Please find attached for your review the document entitled "Site Hydrogeologic Report for Dump Leach Area #3, Barrick Mercur Gold Mine, Utah, for Barrick Resources (USA), Inc." This report is submitted pursuant to Part I, Section E.2(a) and Section H.3(a)-(e) of the above noted permit.

This report accurately and adequately describes the pertinent site hydrogeologic issues expressed by the Bureau of Water Pollution Control during the permit development process. Barrick intends to pursue completion of the shallow groundwater monitoring well as soon as practicable and continue the accelerated groundwater monitoring program to its designed conclusion.

Please contact me at extension 313 should you have any comments on the report or Barrick's implementation schedule.

Respectfully,

Glenn M. Eurick
Environmental Affairs Coordinator (USA)

GME/cg

Attachment

RECEIVED
JUL 31 1990
DIVISION OF
OIL, GAS & MINING

cc/enc: F. D. Wicks
R. R. Sacrison
W. Hedberg (DOGM)
M. Trujillo (Tooele County)

cc: C. L. Landa
E. E. Maurer
T. B. Faddies
M. P. Richardson
D. P. Beatty

Barrick Mercur Gold Mine
P.O. Box 838, Tooele, Utah 84074 Telephone (801) 268-4447 FAX(801) 266-4296