Division of Oil, Gas, & Mining
Mining Report

04/08/92

MINE ID: M045017 MINE NAME: MERCUR MINE

OPERATOR: BARRICK MERCUR GOLD MINES, INC
CONTACT: GLENN M EURICK
ADDRESS: P O BOX 838
TOOELE UT 84074

PHONE: (801)268-4447

Surface Owner: PRIVATE BLM #:
Mineral Owner: PRIVATE Lease #:

Qtr-Qtr-Qtr1	Qtr-Qtr-Qtr1	Qtr1	Qtr-Qtr-Qtr2	Qtr-Qtr-Qtr2	Qtr2	Sec	Range	Town
						4	3.0W	6.0S
						8	3.0W	6.0S
						32	3.0W	5.0S

Permit Status: APP Mine Type [(S)urface, (U)nderground]: S

Mine Status (PRO,ACT,SUS,RET): ACT Acreage: 892

Minerals Mined
AU, AG

DATE RECEIVED	TENTATIVE APPROVAL DATE	FINAL APPROVAL DATE	LAST INSPECTED
03/10/81	05/01/81	10/13/81	09/05/90

BOND TYPE: SELF BOND BOND AMOUNT: 8,808,891

ANNUAL REPORT YEAR: 91

NONCOMPLIANCE NOTICES:	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
VIOLATIONS:	0	DATE ISSUED:	/ /	DATE RESOLVED:	/ /
REVISIONS:	0	DATE REC'D:	/ /	DATE APPROVED:	/ /
AMENDMENTS:	0	DATE REC'D:	/ /	DATE APPROVED:	/ /

COMMENTS:
Inpsection made to discuss ongoing dump leach #3 construction. Also to evaluate cyanide solution spill of 40-60 lbs sodium cyanide. Structures not adequate to handle such a spill of this magnitude. JBR working w/operator to see if a clay cap needs to be installed over dump leach #3.