PLS FILE!

PHONE LOG
Tom Munson

Mine Name: BARRICK **Mine ID Number:** M045/017

Contact: J B BROWN **Date:** 12/12/97

Received Call ✓ **Initiated Call** ____ **Time:** 2:30

463-0902

+ OCTOBER 6, 1997 MEMO +
BAKE ↓ J.B. BROWN SAMPLING CYANIDE

50 FEET OF ALLUVIUM
CONCRETE STRUCTURE

I informed him of the fact that I would have liked a map that showed specifically the location of the sampling points for the storm water sampling. He stated that the reason for the cyanide was that the historic tailings ~~which~~ have cyanide in them and it leaks out. The other samples were taken from the pit samples into the Golden Gate Pit.

The second issue is the final reclamation channel into the Golden Gate Pit and the use of the concrete inlet structures. I recommended that no concrete inlet structures be used and competent bedrock or inlet areas be found.

phone.log