State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

April 20, 2001

CERTIFIED RETURN RECEIPT
7000 0520 0021 7582 9064

Mr. Jim Huizingh
Morton International, Inc.
P.O. Box 506
I-80 West Exit 84
Grantsville, Utah 84029

Re: Five-Year Review of Reclamation Surety Estimate, Morton International, Inc., Morton Salt\Grantsville, M/045/037, Tooele County, Utah

Dear Mr. Huizingh:

The Division is performing the periodic review of reclamation surety estimates to verify their accuracy and make adjustments for escalation and any site modifications that could result in a change of the surety amount presently being held for the site. Division policy requires that surety estimates being held by the State include a five year escalation and be reviewed every five years. A number of these five-year reviews are overdue and were postponed due to higher permitting priorities.

The reclamation surety for Morton International, Inc.'s Morton Salt\Grantsville was due for review as of 1998. To assist us in this review, we request an updated map of your site showing current surface facilities and disturbances. Please provide the updated map at a scale of not less than 1 inch = 500 feet, which includes: buildings, stationary mining/processing equipment, roads, utilities, power lines, drainage structures (i.e. berms, culverts, etc.), topsoil, ore and product storage areas, overburden/waste dumps, tailings or processed waste facilities, solid and liquid wastes, and wastewater discharge treatment and containment facilities, etc. This map should include all areas which have been affected by this operation to date. Please ignore items listed above which do not apply to your site.

If any reclamation has been completed on the site since the last surety estimate review, please provide a separate map of the same scale as the site map, clearly identifying these reclaimed

areas, the acreage affected, and the date of the reclamation. Please cross-hatch or shade the areas to identify the reclamation treatments (i.e. ripping, regrading, mulching, seeding, etc.) which have been applied.

Please provide this information within the next 60 days or no later than June 20, 2001. If you are unable to provide this information in this time frame, please contact the Division with justification for requesting additional time. Thank you for providing this information to assist us in our surety estimate review. If you have any questions concerning this letter, please contact Doug Jensen at (801) 538-5382.

Sincerely,

Doug Jensen

for
D. Wayne Hedberg
Permit Supervisor
Minerals Regulatory Program

jb
M45-37.bndrvw.doc