JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program

October 10, 2006

Supervisor

Mine Name: ~~North Slope~~ (Allred)
Operator Name: Interstate Brick Company

Permit number: M0490029
Inspection Date: August 22, 2006
Time: 9:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: John Hewitt

Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	☒	☒	☐
2. Public Safety (shafts, adits, trash, signs, highwalls)	☒	☐	☐
3. Protection of Drainages / Erosion Control	☐	☐	☐
4. Deleterious Material	☐	☐	☐
5. Roads (maintenance, surfacing, dust control, safety)	☐	☐	☐
6. Concurrent Reclamation	☐	☐	☐
7. Backfilling/Grading (trenches, pits, roads,	☒	☐	☐
8. Soils	☐	☐	☐
9. Revegetation	☐	☐	☐
10. Other	☐	☐	☐

Purpose of Inspection:
Routine Inspection while in the area..

Inspection Summary:
The LMO for this site was approved March 28, 2006. While there was no activity at this site during this inspection, there was evidence of recent activity and a front-end loader at the site. Because of the secluded nature of this site there is an ongoing problem with other people dumping trash. The operator had just recently hauled out a truckload of domestic garbage that someone had dumped. (since access to this site is signed and gated, it is amazing how they get in!). No non-compliance problems were noted during the inspection.

Photos were taken to document site conditions.

Conclusions and Recommendations:
Continue to monitor the site when in the area.

Inspector's Signature _____ **Date:** October 10, 2006

LK:pb
O:\M049-Utah\S0490028-NorthSlope\inspections\insp-08222006.doc