JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
April 17, 2007

Supervisor _____

Mine Name: Elite Rock West (Wasatch Graystone Rock Products)
Permit number: S/049/050
Operator Name: Wasatch Mountain Excavating, Inc
Inspection Date: April 4, 2007
Time: 11:00 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: None
Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	☒	☒	☐
2. Public Safety (shafts, adits, trash, signs, highwalls)	☒	☐	☐
3. Protection of Drainages / Erosion Control	☐	☐	☐
4. Deleterious Material	☐	☐	☐
5. Roads (maintenance, surfacing, dust control, safety)	☐	☐	☐
6. Concurrent Reclamation	☐	☐	☐
7. Backfilling/Grading (trenches, pits, roads, highwalls,	☐	☐	☐
8. Soils	☐	☐	☐
9. Revegetation	☐	☐	☐

Purpose of Inspection:
Routine inspection while in the area.

Inspection Summary:
The secondary access to this site (adjacent to the tunnel waste dump has been blocked off to control access to this site. Operations have not expanded (aerially, but have deepened).

The equipment operator was asked about the new permit for Wasatch Mountain (Wasatch Graystone Rock Products) that was recently received by the Division. He Called the the office to find out and was informed that this was not a new NOI, but the replacement pages requested by DOGM to change the name of this operation. This greatly clarified this situation.

Photos were taken to document site conditions.

Conclusions and Recommendations:
Inform management that the new NOI received is replacement pages to change the name of the Elite West Quarry to Wasatch Graystone Rock Products.

Continue to monitor reclamation success when in the area.

Inspector's Signature _____

LK:pb
O:\M049-Utah\S0490050-EliteRockWest\inspections\Insp-04042007.doc