

File Exp: Valley Camp
Reply 12/6/78
JMP

0005 VALLEY CAMP OF UTAH, INC.

Scofield Route
Helper, Utah 84526

December 4, 1978

Mr. Mike Thompson
Engineering Geologist
Division of Oil Gas & Mining
1588 West North Temple
Salt Lake City, Utah 84116



Re: Valley Camp of Utah
Exploratory Drilling

Dear Mr. Thompson:

We have just completed our exploratory drilling and wish to inform you of the results. Because of insufficient results from Hole No. 2 (78-30-1) as listed in my letter of November 20, 1978, we drilled an additional two holes very near the location of that hole. The additional two holes were drilled in order to better locate the O'Connor fault through that area.

Hole No. 1 as listed was not drilled due to adverse weather conditions.

All three holes were drilled to 8 inches and no new access roads were required. Related information as required by Rule M-3 (5) is as follows:

1. Hole Number	78-30-1	78-30-2	78-30-3
2. Date Drilled	11-29-78	11-30-78	12-01-78
3. Hole Location	All located in SW $\frac{1}{4}$ Section 30 T 13 S R 7 E		
4. Total Depth	404'	342'	246'
5. Depth to Ground Water	Dry	Dry	Dry
6. Water Bearing	-	-	-
7. Water Quality	-	-	-
8. Water Quantity	0	0	0
9. Plugging Method	Cement	Cement	Cement

All three holes will be plugged at the surface only, since water was not encountered.

Drill hole No. 78-30-2 is located approximately 500 ft. east of hole No. 78-30-1 on a pre-existing access road.

Mr. Mike Thompson
Page 2
December 4, 1978

Drill hole No. 78-30-3 is located on the same road approximately 500 ft. further east of hole No. 78-30-2. Reclamation activities concerning these holes will commence as soon as weather conditions permit.

Sincerely,



Trevor G. Whiteside
Senior Mine Engineer

tgw:vy

cc: W. H. Haynes, Jr.