

ACT 1007/014



SCOTT M. MATHESON  
Governor

OIL, GAS, AND MINING BOARD

GORDON E. HARMSTON  
Executive Director,  
NATURAL RESOURCES

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS, AND MINING  
1588 West North Temple  
Salt Lake City, Utah 84116  
(801) 533-5771

CHARLES R. HENDERSON  
Chairman

CLEON B. FEIGHT  
Director

JOHN L. BELL  
C. RAY JUVELIN  
THADIS W. BOX  
CONSTANCE K. LUNDBERG  
EDWARD T. BECK  
E. STEELE McINTYRE

October 17, 1980

#5776504

REGISTERED RETURN RECEIPT REQUESTED

Mr. Trevor Whiteside  
Mine Engineer  
Valley Camp of Utah, Inc.  
P. O. Box 507  
Clear Creek, Utah 84517

RE: Violation Termination

Dear Mr. Whiteside:

In reference to the October 2, 1980, inspection of the Utah #2 Mine, the following violations are hereby terminated.

Violation #80-1-3-2, #1 of 2

Rule MC 717.17(a)

Failure to pass surface drainage from the disturbed area through a sedimentation pond.

Violation #2 of 2

Rule MC 717.17(j)(3)(ii)

Failure to maintain ditches and culverts.


In addition, please refer to the Division directive issued August 28, 1980, that specifically outlines compliance requirements for the #2 sediment pond at the Utah #2 Mine. Additional riprapping of inlet structures and installation of drop inlet drains and culverts are to be completed by no later than November 1, 1980. Action to be taken in reference to the Division directive issued August 28, 1980, should consist at a minimum of the following:

Mr. Trevor Whiteside  
October 17, 1980  
Page two

- A) Remove the telephone pole at the upper corner of the #2 sediment pond at the Utah #2 Mine or submit adequate data supporting a 1.5 static safety factor of the inslopes of the sediment pond.

If you have any questions, please contact the Division.

Sincerely,



JOSEPH C. HELFRICH  
RECLAMATION SOILS SPECIALIST

cc: Tom Ehmett, OSM

JCH/btm