

March 12, 1981

Inspection Memo  
to Coal File:

RE: Valley Camp of Utah, Inc.  
Utah #2  
ACT/007/~~014~~ 014  
Carbon County, Utah

On February 17, 1981, Division inspectors Sandy Pruitt and Tom Portle visited the Utah #2 loadout facility. They were accompanied by Trevor Whiteside, Senior Mining Engineer for Valley Camp of Utah, Inc. The purpose of the visit was to perform a monthly partial inspection.

With regard to areas of concern identified during the December 12, 1980 inspection, some progress has been made and some additional maintenance work is required.

#### Work Accomplished

Slopes on the east side of the disturbed area have been hydromulched by Ellis and Sons during January, 1981.

The following areas were in need of attention during the December 12, 1980 inspection. On the February 17, 1981 inspection these culvert maintenance problems persisted.

#### Recommendations

1. Clean culvert south of tipple,
2. Clean debris in culvert under conveyor which empties into south sediment pond,
3. Repair, replace or remove culvert along areas adjacent to road and drainage into south sediment pond.

Inspection Memo to Coal  
ACT/007/014  
March 12, 1981  
Page Two

These areas are potentially in violation and should be corrected prior to the next inspection.

Mr. Whiteside was informed of perimeter marker requirements, buffer zone sign requirements and concerns expressed in guidelines set forth in Environmental Criteria for Electrical Transmission System.

THOMAS L. PORTLE <sup>TLP</sup>  
RECLAMATION OFFICER

cc: Tom Ehmett, O.S.M.  
Trevor Whiteside, Valley Camp

Note: For statistics see Blazon memo dated 3/2/81.  
(Grant A&E)