

0010



SCOTT M. MATHESON —
Governor

OIL, GAS, AND MINING BOARD

CHARLES R. HENDERSON
Chairman

GORDON E. HARMSTON
Executive Director,
NATURAL RESOURCES

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS, AND MINING
1588 West North Temple
Salt Lake City, Utah 84116
(801) 533-5771

CLEON B. FEIGHT
Director

JOHN L. BELL
C. RAY JUVELIN
THADIS W. BOX
MAXILIAN A. FARBMAN
EDWARD T. BECK
E. STEELE McINTYRE

March 20, 1981

#0367367

REGISTERED - RETURN RECEIPT REQUESTED

Mr. Trevor G. Whiteside
Senior Mining Engineer
Valley Camp of Utah, Inc.
Scofield Route
Helper, Utah 84526

RE: Areas of Concern at Utah #2 Mine
ACT/007/014
Carbon County, Utah

Dear Mr. Whiteside:

As we discussed during the December 12, 1980 complete inspection and during the February 17, 1981 partial inspection there are some culvert maintenance problems at the Utah #2 loadout facility. These are discussed in more detail in the enclosed memo.

Valley Camp of Utah, Inc. is to be commended for their diligent efforts at establishing vegetation at both Utah #2 and Belina.

If you have any questions, please feel free to call.

Sincerely,

THOMAS L. PORTLE
RECLAMATION OFFICER

TLP/te

Enclosure