

VALLEY CAMP OF UTAH, INC.

Scofield Route

0041

Helper, Utah 84526

9 November 1982

RECEIVED
NOV 09 1982

Mr. Thomas N. Tetting
Division of Oil, Gas & Mining
4241 State Office Building
Salt Lake City, Utah 84114

DIVISION OF
OIL, GAS & MINING

Re: Supplemental Response to Apparent
Completeness Review Comments

Dear Mr. Tetting:

I have attempted to respond to all the comments disclosed under cover of your August 25, 1982, letter to Mr. William H. Haynes, Jr., concerning the Apparent Completeness Review of the Valley Camp Mining and Reclamation Plan (MRP):

Certain portions of your comments have been addressed, but there are yet some areas which I am still waiting for information on. Accordingly, the four (4) sections listed below have not been addressed. As soon as possible, I will address these areas and a response for each will be issued.

Revised comments for the other areas have been enclosed for insertion into the ACR (Volume V), delivered to your office on June 10, 1982, and also, Volume III of the original MRP submitted.

The responses are submitted in two (2) groups. Comments comprising Group 1 (pages numbered at bottom of page) are either replacements for corresponding page numbers or inserts as numerically appropriate into Volume V (black binder). Those pages found in Group 2 (numbered at the top of each page) are either replacements for corresponding page numbers or new inserts for the blue Volume III, as page numbers would indicate.

The following sections of the Division's ACR comments have not been included in this package:

1. Section UMC 783.14 - Geology Description. The consultants working on this section are yet unfinished.

Mr. Thomas N. Tetting
9 November 1982
Page 2

2. Section UMC 784.13 - Reclamation Plan - General Requirements. The Forest Service flight has been postponed due to inclement weather, and as a result, we have not been able to produce the maps required for proper response to this section.
3. Section UMC 784.13 - Revegetation. This section also delayed for reasons indicated above.
4. Section UMC 784.13 - Backfilling and Grading. This section also delayed for reasons indicated above.

Enclosed, please find ten (10) copies of each revision separated into two (2) previously mentioned groups; ten (10) copies of Plate 6A, Groundwater Contours, and ten (10) copies of Reclamation Map D-1 (Rev. 2).

Plate 6A should be inserted into the Vaughn Hansen Associates Hydrologic Inventory Report as a supplement to Plate 6, and the Revised Reclamation Map D-1 should replace the same numbered map (Rev. 1) previously submitted in Volume V.

In addition, I am enclosing ten (10) copies of the Golder Report (excluding figures already submitted) for inclusion into Volume V as part of Appendix A. This will place the entire report in one location. Previously, the report has been submitted proportionately in different sections.

Please issue copies of each enclosure to whatever groups are entitled.

Every effort will be made to expedite a response to the unfinished sections.

If you have any questions concerning this submittal, please call me.

Sincerely,



T. G. Whiteside
Chief Engineer

Enclosures