

0007

March 8, 1982

Inspection Memo
to Coal File:

RE: Utah #2 Loadout
Valley Camp of Utah, Inc.
ACT/007/014
Carbon County, Utan

On March 3, 1982, Ken Wyatt and Sandy Pruitt inspected the Utah #2 laodout as a follow-up to concerns noted during a January 25, 1982, inspection. Trevor Whiteside of Valley Camp, accompanied the inspectors on a tour of the lower pad area to determine if the drainage system to sediment pond #2 had been maintained as required.

The coal and snow residue in and adjacent to the sediment pond inlet was frozen and could not be removed as requested. A depression was excavated in order to retain ponding resulting from slow infiltration under the snow at the inlet. Mr. Whiteside informed inspectors that the State Highway Department had been pushing snow to the side of the road and sediment pond, thereby contributing to the problem. Road surface grades and ditches were being maintained at the time of the inspection. No violations were evident.


SANDY PRUITT
RECLAMATION OFFICER

cc: Tom Ehmett, OSM
Trevor Whiteside, Valley Camp
Inspection Staff

SP/btb

Statistics:

Vehicle: #EX 45424--543 miles
Per Diem: 2 persons X 2 days, 9 hours @ \$104.91/person = \$205.82
Grant: A & E