



STATE OF UTAH
 NATURAL RESOURCES & ENERGY
 Oil, Gas & Mining

Scott M. Matheson, Governor
 Temple A. Reynolds, Executive Director
 Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

August 6, 1982

0021

ACT/007/001

Mr. Larry Dalton
 Division of Wildlife Resources
 Southeastern Regional Office
 455 West Railroad Avenue
 Price, Utah 84501

RE: Record of Telephone Conversation
 w/ Larry Dalton, Wildlife Biologist

DATE: August 5, 1982
TIME: 1:45 p.m.
SUBJECT: Sediment Loading in Eccles Creek

Dear Mr. Dalton;

The following information is being provided to you as documentation of our telephone conversation dated August 5, 1982. During our conversation, you indicated that approximately 1.5 miles of Eccles Creek was being effected by sediment loading from Valley Camp's Belina operation. Specifically mentioned, was the the overflow from two 12,000 gallon water tanks travelling across portions of the Belina disturbed area, down a portion of the main access and haul road, and then into Whiskey Creek. In a subsequent phone conversation with Mr. Ed Foust of Valley Camp of Utah, Inc., I was informed by Mr. Foust that the source of the problem stemmed from a cut wire that provided electrical power to the automatic float system to the two 12,000 gallon water tanks, which regulated the flow in the tanks. Mr. Foust also indicated that an electrician had been requested to repair the severed wire on Friday, August 6, 1982. According to Ed, the flow had stopped as of 11:00 a.m., Thursday, August 5, 1982. However, should flow resume, it would be diverted to the existing Belina sediment pond until the electrical problem is alleviated.

Thank you for informing the Division of this matter.

Sincerely,

Joseph C. Helfrich
 JOSEPH C. HELFRICH
 FIELD SUPERVISOR

JCH/tck

cc: D. W. Hedberg, DOGM
 Trevor Whiteside, Valley Camp of Utah, Inc.
 Ed Foust, Valley Camp of Utah, Inc.
 Inspection Staff