



STATE OF UTAH
 NATURAL RESOURCES & ENERGY
 Oil, Gas & Mining

Scott M. Matheson, Governor
 Temple A. Reynolds, Executive Director
 Cleon B. Feight, Division Director

4241 State Office Building • Salt Lake City, UT 84114 • 801-533-5771

0022

August 6, 1982

107/007/001

Mr. Ed Foust
 Valley Camp of Utah, Inc.
 P.O. Box 507
 Clear Creek, UT 84517

RE: Record of Telephone Conversation
 with Mr. Ed Foust
 Mine Engineer
 Valley Camp of Utah, Inc.

DATE: August 5, 1982
TIME: 2:30 p.m.
SUBJECT: Water Tank Overflow Discharge

Dear Mr. Foust;

On August 5, 1982 at approximately 2:30 p.m., we discussed the water tank discharge problem at the Belina operation. During the conversation you indicated that the problem was caused by a severed electric wire which operated the automatic float system in the water tanks. An electrician had been requested to correct the problem on Friday, August 6, 1982. If the electrical problem could not be corrected, any discharge from the water tanks would be diverted into the existing sediment pond for the Belina mine. When the electrical problem has been corrected, would you please notify the Division and/or Larry Dalton of Wildlife Resources? He can be contacted in Price at 637-3310.

Thank you very much.

Sincerely,

Joseph C. Helfrich

JOSEPH C. HELFRICH
 FIELD SUPERVISOR

JCH/tck

cc: Larry Dalton, Wildlife Resources
 D.W. Hedberg, DOGM
 Inspection Staff