

*Hand,*  
*- Please review & file.*  
Page 1 of 2 Pages  
*End 12/21/83*

United States Department of the Interior  
Office of Surface Mining  
Mine Site Evaluation Inspection Report

For Office Use Only

1a	1b	1c
Y Y M M	Batch	Report

2. Name of Permittee  
VALLEY CAMP OF UTAH

3. Street Address  
SCOFIELD RT

4. City  
HELPER

5. State  
UT

6. Zip Code  
84526

7. Area Code  
801

8. Telephone Number  
448-9413

9. MSHA Number

10. Date of Inspection (Y Y M M D D)  
83/208

11. State Permit Number  
ACT 007 001

12. Name of Mine  
BELINA-UTAH #2

13. County Code  
007

14. State Code  
UT

15. Strata

16. State Area Office  
01

17. OSM Field Office No.  
02

18. OSM Area Office No.

19. OSM Sample No.

20. Type of Inspection (Code)  
TDF

21. Joint Inspection  
Yes No

22. Inspector's ID No.  
031

23. Status

- A  02 Type of Permit
- B  A Mine Status (Code)
- C  20+34 Type of Facility (Code)
- D  03136.0 Number of Permitted Acres
- E  00050.0 Number of Disturbed Acres

24. Type of Activity (check applicable boxes).

- A  Steep Slope
- B  Mountain Top Removal
- C  Prime Farmlands
- D  Alluvial Valley Floors
- E  Anthracite
- F  Federal Lands
- G  Indian Lands
- H  Other

25. Performance Standards (Codes)

Instructions: Indicate compliance code. For any standard marked 2 or 3 provide narrative to support this determination.

Standards That Limit the Effects to the Permit Area

- A  Distance Prohibitions
- B  Mining Within Permit Boundaries
- C  Signs and Markers
- D  Sediment Control Measures
- E  Design and Certification Requirements—Sediment Control
- F  Effluent Limits
- G  Surface Water Monitoring
- H  Ground Water Monitoring
- I  Blasting Procedures
- J  Haul/Access Road Design and Maintenance
- K  Refuse Impoundments
- L  Other: Specify \_\_\_\_\_

Standards That Assure Reclamation Quality and Timeliness

- M  1 Topsoil Handling
- N  Backfilling and Grading
- O  Following Reclamation Schedule
- P  Revegetation Requirements
- Q  Disposal of Excess Spoil
- R  Handling of Acid or Toxic Materials
- S  Highwall Elimination
- T  Downslope Spoil Disposal
- U  Post Mining Land Use
- V  Cessation of Operations: Temporary
- W  Other \_\_\_\_\_

*Other standards not checked during this follow up*

## United States Department of the Interior Office of Surface Mining Mine Site Evaluation Inspection Report

26. State Permit Number

27. Date of Inspection  
(Y Y M M D D)

ACT 007 001

831208

28.  Yes  No Do mining and reclamation activities on the site comply with the plans in the permit?  
If no, provide narrative to support this determination.

29. Indicate number of complete and partial inspections conducted by the State to date for this annual review period:

29a.  Number of Completes

29b.  Number of Partials

30. Indicate number of complete and partial inspections required by the State during this annual review period:

30a.  Number of Completes

30b.  Number of Partials

31. Has inspection frequency been met?

31a.  Yes  No Completes

31b.  Yes  No Partials

32. FEDERAL ENFORCEMENT INFORMATION. [Enter violation number. Check appropriate box(es)]

Ten-Day Notice No.	Notice of Violation No.	Cessation Order No.	Violation Codes
<input type="text"/>	<input type="text"/>	<input type="text"/>	
A <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Authorizations to Operate
B <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Signs and Markers
C <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Backfilling and Grading
D <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Highwall Elimination
E <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Rills and Gullies
F <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Improper Fills
G <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Topsoil Handling
H <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Sediment Ponds
I <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Effluent Limits
J <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Water Monitoring
K <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Buffer Zones
L <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Roads
M <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Dams
N <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Blasting
O <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Revegetation
P <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Spill on the Downslope
Q <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Mining Without Permit
R <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Exceeding Permit Limits
S <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Distance Prohibitions
T <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Toxic Materials
U <input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Other Violations

33. Name of Authorized Representative (print or type)

<i>Frank Atencio</i>	Date	00	0
Signature of Authorized Representative	Date	05	0
<i>Frank Atencio</i>	Dec 24, 1983	03	0
Signature of Reviewing Official	Date	01	0
<i>Tom G. Green</i>	12/22/83		

MINE SITE EVALUATION REPORT NARRATIVE

VALLEY CAMP OF UTAH  
Scofield Rt.  
Helper, UT 84526

BELINA-UTAH #2

INSPECTION DATE: December 8, 1983; ACT/007/001

INSPECTOR: Frank Atencio, #031

This Ten-Day Notice follow-up inspection was conducted along with Steve Tanner of Valley Camp of Utah, Inc.

Follow-up inspection to Ten-Day Notice No. 83-II-242-11 issued for failure to protect topsoil substitute material from erosion and contamination. The topsoil substitute material is stored at the Utah No. 2 loadout facility.

Follow-up findings - Mr. Tanner explained that all debris had been removed from the topsoil substitute stockpiles. Some of the stockpiles were removed and consolidated with other stockpiles. Also despite 30" of snow on the ground this inspector was able to see the straw bales placed around the three stockpiles to provide protection.

This follow-up inspection revealed that the operator had taken appropriate action to correct the problem resulting in the issuance of this Ten-Day Notice.