

December 24, 1984

TO: Coal File, Inspection and Enforcement
FROM: Sandy Pruitt, Mining Field Specialist *SP*
Re: Belina Complex, Valley Camp of Utah Inc., ACT/007/001,
Folder #7, Carbon County, Utah

The above mentioned operation was inspected by Sandy Pruitt on December 13, 1984. Steve Tanner represented Valley Camp on this inspection. On December 13, 1984, the Belina Mine Sediment Pond was inspected. There was no fluctuation in the pond water level since the November 27, 1984 inspection, which might be indicative of mine discharge into the sediment pond or utilization of the decant structure which has not yet been approved by DOGM.

Snow disposal operations at the Utah loadout are still poor. Some disturbed area snow has been pushed against the drainage control berms by the bathhouse and by the undisturbed bypass culvert adjacent to the lump coal loadout. Snow is contained inside the berms but this practice, if continued, is likely to result in disturbed area snow being pushed into undisturbed areas, which will warrant a violation.

re

cc: Steve Tanner, Valley Camp
Donna Griffin, OSM
Joe Helfrich, DOGM

Statistics: See Skyline memo dated December 24, 1984
0032Q-20