

0010

File

May 2, 1985

TO: Coal File, Inspection and Enforcement Folder
FROM: Sandy Pruitt, Mining Field Specialist *SP*
RE: Belina Mine Complex, Valley Camp Inc., ACT/007/001, Folder #7, Carbon County, Utah

The partial inspection of the Belina Mine and loadout was conducted by Sandy Pruitt and Steve Tanner on April 25, 1985. Heavy snow showers and runoff were occurring at the time of this inspection. All drainage control measures inspected were functional. Steve Tanner mentioned that the Utah Fuel Railroad contractor had not yet repaired the drainage control ditch across from the Utah #2 portals which has resulted in ponding on the pad area. There is no potential for release of disturbed area drainage offsite.

The abatement plans for NOV #N85-2-3-2 were submitted for DOGM review on April 11, 1985 and approved on April 29, 1985. NOV #N85-2-3-2 was terminated following this inspection effectively April 11, 1985.

The Belina Mine Sediment Pond was discharging at the time of this inspection. The decant valve was completely opened and water also passed through the tear in the standpipe from ice damage. The sediment pond discharge passes through a filter sock at the culvert outlet. Samples of the discharge are obtained and are currently being analyzed for suspended solid, settleable solids, total dissolved solids and for oil and grease.

re

cc: Donna Griffin, OSM
Steve Tanner, Valley Camp
Joe Helfrich, DOGM

Statistics: See Deer Creek Mine memo dated May 2, 1985

0242Q-2