



FILE COPY

Act 0071 of

Mike File
S. Linder

Norman H. Bangerter
Governor

Suzanne Dandoy, M.D., M.P.H.
Executive Director

0050

October 16, 1986
538-6146

RECEIVED
OCT 20 1986

DIVISION OF
OIL, GAS & MINING

Mr. T. G. Whiteside
Valley Camp of Utah, Inc.
Scofield Route
Helper, Utah 84526

RE: Belina Mine
Sediment Pond Cleanout and
Disposal

Dear Mr. Whiteside:

We have reviewed your request dated August 26, 1986, for changing the method of cleanout and disposal of sediment from pond no. 4 at the Belina Mine. The proposed change includes pumping of sediment in slurry from the pond and disposal of the slurry in the Belina Mine. The proposed disposal area in the mine is currently flooded. Water from the disposal area will be utilized for making the slurry.


We do not have an objection to the proposed change as outlined above provided the following conditions are met:

1. Pumping operations associated with cleaning the pond shall be discontinued during periods of precipitation.
2. There shall be no discharge from the pond during cleaning.
3. There shall be no mixing of water from the pond or from the proposed disposal area of the mine.
4. State and Federal discharge limitations must be met at all times during cleanout.

If you have any questions, please contact David Ariotti of my staff at 637-3671.

Sincerely,

UTAH WATER POLLUTION CONTROL COMMITTEE


Calvin K. Sudweeks
Executive Secretary

DRA:jgh

cc: Oil, Gas & Mining

David Ariotti, Southeastern District Health Dept.

Kenneth L. Alkema, Director • Division of Environmental Health

0053

Mine file
ACT/007/001
Belina Complex
#7?

VALLEY CAMP OF UTAH INC.
IMPREST ACCOUNT
SCOFIELD ROUTE
HELPER, UTAH 84526

2983

97-51/1243

1277

Oct. 21 19 86

Pay to the order of STATE OF UTAH-DIV. OIL, GAS & MINING \$ 130.00

ONE HUNDRED THIRTY & NO/100 Dollars



First Interstate Bank of Utah
Price Office
82 West Main Street
Price, Utah 84501

For Assessment-State Violation W 86-9-8-1

John B. [Signature]

ACT/007/001 @002983@ 1:124300518: 51 01080 9@

Rocky Mountain Bank Note A