



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

0016

Norman H. Bangertor Governor
Dee C. Hansen Executive Director
Dianne R. Nielson, Ph.D. Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

Permittee and/or Operators Name: Valley Camp of Utah, Inc.
 Business Address: Scotfield Bonte of Helper, UT 84526
 Mine Name: Belina Complex Permit Number: ACH/007/001
 Type of Mining Activity: Underground Surface Other
 County: Carbon
 Company Official(s): Trevor Whiteside
 State Official(s): Holland Shepherd
 Inspection Date and Time: 8-14-86 9:30 - 11:00
 Partial: Complete: Date of Last Inspection: 7-18-86
 Weather Conditions: cloudy-cool
 Acreage: Permitted 2832 Disturbed 99 Regraded 0 Seeded 0 Bonded 79
 Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. SIGNS AND MARKERS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. TOPSOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DIVERSION'S	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. SEDIMENT PONDS AND IMPOUNDMENTS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
d. OTHER SEDIMENT CONTROL MEASURES	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
e. SURFACE AND GROUNDWATER MONITORING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f. EFFLUENT LIMITATIONS	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
5. EXPLOSIVES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. COAL PROCESSING WASTE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. NONCOAL WASTE	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. SLIDES AND OTHER DAMAGE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. CONTEMPORANEOUS RECLAMATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. BACKFILLING AND GRADING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. REVEGETATION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. SUBSIDENCE CONTROL	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. CESSATION OF OPERATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16. ROADS				
a. CONSTRUCTION	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b. DRAINAGE CONTROLS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c. SURFACING	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
e. MAINTENANCE	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. OTHER TRANSPORTATION FACILITIES	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT
(Page 2)

Permit Number: ACT/007/001

Date of Inspection: 8-14-86

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

4. c Sediment Ponds:

The operator is currently cleaning sediment pond #4. A dredging pump has been leased, by the operator to facilitate sediment removal from the pond. Slurry is currently being pumped into the mine, sediment deposited in a sump, then the water is pumped back into the sediment pond. Two six inch pipes have been installed side by side from the pond to the mine portal. The pond was not discharging at the time of inspection. Providing no heavy rains develop in the area during the time of pond cleaning, discharge should not occur. Infact, the pond's water level should decline substantially.

4. c. Sediment Control Measures:

An inspection was made of the area concerned in N86-9-8-1. The operator had installed straw bales around the pipe disturbance area and straw bales in the ditch which treats haul road drainage. Also the area disturbed by the pipe installation had been reseeded. I terminated the NoV effective the date work had been completed at the site(7-24-86). I inspected the site on 7-23-86, at that time all but the reseeding had to be completed.

4. f. Effluent limitations:

Samples where collected from the discharge of the new pipe installed at NPDES discharge point #5. The pipe originates from an abandoned, sealed-off portion of the mine. Water from the discharge, on visual inspection, looked very clean.

8. Noncoal Wastes:

Small oil spills are currently being contained around the Belina oil storage facility, however preventive maintenance is advised. The berm behind the facility on the east side requires attention to insure containment of spills.

Copy of this Report:

Mailed to: Trevor Whitehead, Donna Griffin

Given to: Joe Helton, Sue Linner

Inspectors Signature and Number:

Walter Stupl #7

8-22-86

0365Q 1-2