

*File*

*SCC* *gd*



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: 2-24-87  
12:30 to 1:30

Permittee and/or Operators Name: Valley Camp of Utah, Inc.  
Business Address: Scofield Route Helper, Ut 84526  
Mine Name: Belina Complex Permit Number: ACT/007/001  
Type of Mining Activity: Underground  Surface Other  
County: Carbon  
Company Official (s): Steve Tanner  
State Official(s): Holland Shepherd  
Partial:  Complete:            Date of Last Inspection 1-14-87  
Weather Conditions: Cloudy, cold, approximately 1.5 feet of new snow on ground  
Acreage: Permitted 2837 Disturbed 79 Regraded 0 Seeded 0 Bonded 79  
Enforcement Action: none

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION 2-24-87

(Comments are Numbered to Correspond with Topics Listed Above)

4.c. Sediment Ponds:

1. The operator's sediment pond number 4 was not discharging at the time of inspection. The pond's water level is still 5 to 6 feet below the discharge point. Lack of snowfall this winter and the pond's cleaning last fall, have contributed to lessen the likelihood of discharge from the pond.
2. The operator's mine water pond number 5 was not discharging at the time of this inspection.

4.d. Other Sediment Controls:

1. Overall sediment control measures at the Belina site and the Utah # 2 loadout site were working adequately during this inspection. One and one-half feet of new snow had fallen the night before this inspection and small snow flurries were still taking place during the inspection. Some snow was melting and flowing into the sediment ponds. The operator had been removing snow from roads and work areas since early morning. No snow stockpiling material had been placed off the disturbed areas.
2. A notable development has occurred in respect to the Belina haul road turn-in area. The turn-in, or approach, is located where the Belina haul road meets the public road or Eccles Creek road. According to a letter I requested from the Utah Department of Transportation (see attached letter) dated 2-18-87, the approach to the Belina haul road from the Eccles Creek road is within the UDOT right-of-way. This area has been in dispute lately regarding the operator's responsibilities concerning drainage controls and snow removal practices. According to the UDOT letter the area is within the 150 foot right-of-way and is meant to be used as an area to stockpile and control snow (from the public road) in the winter time.

The operator will no longer be held responsible for drainage control or snow removal in this area. The operator will, however, remain responsible for drainage or snow coming off the Belina haul road which runs across or effects the UDOT right-of-way.

Copy of this Report:

Mailed to: Steve Tanner, Donna Griffin  
Given to: Joe Helfrich

Inspectors Signature and Number: Holland Shepherd Date: 3-3-87