



RE 375-87

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

File

gd

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 3-11-87
10:00 to 12:00

Permittee and/or Operators Name: Valley Camp of Utah, Inc.
Business Address: Scofield Route Helper, Ut 84526
Mine Name: Belina Complex Permit Number: ACT/007/001
Type of Mining Activity: Underground Surface Other
County: Carbon
Company Official (s): Steve Tanner
State Official(s): Holland Shepherd, Bill Malencik
Partial: Complete: Date of Last Inspection: 3-6-87
Weather Conditions: Cloudy, cold, snowing and windy, some runoff occurring
Acreage: Permitted 2837 Disturbed 79 Regraded 0 Seeded 0 Bonded 79
Enforcement Action: N87-9-1-1 Termination

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	(X)
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION 3-11-87

(Comments are Numbered to Correspond with Topics Listed Above)

4.d. Other Sediment Control Measures:

This inspection was conducted with the main intent being the evaluation of the site associated with N87-9-1-1 (written during the 3-6-87 inspection) and termination of the NOV. During the previous inspection, I wrote this violation in connection with some debris that had been pushed down the embankment of the substation service road. I terminated the violation during the current inspection because the requirements specified in the NOV had been satisfied. The operator had removed all the material which had been pushed over the side and pushed back piled debris from the edge of the road, to avoid further sediment loading to Whiskey Creek.

16.e. Road Maintenance:

The operator was involved in the cleaning of material (snow, rocks, and mud) from the Belina haul road ditch during the course of this inspection and had been working on the ditch most of the week. The material in the ditch was not blocking the flow of runoff.

Copy of this Report:

Mailed to: Steve Tanner, Donna Griffin

Given to: Joe Helfrich, Bill Malencik

Inspectors Signature and Number: Holland Shepherd Date: 3-16-87