



Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

REVISED

**INSPECTION REPORT**

INSPECTION DATE & TIME: Aug. 25, 1988  
9:00 a.m. to 2:00 p.m.

Permittee and/or Operators Name: Valley Camp of Utah  
Business Address: Scotfield Route Helper, Utah 84526  
Mine Name: Belina Complex Permit Number: ACT/007/001 7010  
Type of Mining Activity: Underground  Surface  Other   
County: Carbon State: Utah  
Company Official (s): Barry Barnum and Steve Tanner  
State Official(s): Daron Haddock and Bill Warmack  
Partial:  XX Complete:  Date of Last Inspection: July 29, 1988  
Weather Conditions: Partly cloudy and warm  
Acreage: Permitted 3136 Disturbed 79 Regraded        Seeded        Bonded 79  
Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. <u>PERMITS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
2. <u>SIGNS AND MARKERS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
3. <u>TOPSOIL</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
b. <u>DIVERSIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
f. <u>EFFLUENT LIMITATIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
5. <u>EXPLOSIVES</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
7. <u>COAL PROCESSING WASTE</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
8. <u>NONCOAL WASTE</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
9. <u>PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
10. <u>SLIDES AND OTHER DAMAGE</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
11. <u>CONTEMPORANEOUS RECLAMATION</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
12. <u>BACKFILLING AND GRADING</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
13. <u>REVEGETATION</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
14. <u>SUBSIDENCE CONTROL</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
15. <u>CESSATION OF OPERATIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
b. <u>DRAINAGE CONTROLS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
c. <u>SURFACING</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
d. <u>MAINTENANCE</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
17. <u>OTHER TRANSPORTATION FACILITIES</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>

INSPECTION REPORT  
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION Aug. 25, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Mr. Barry Barnum accompanied Bill Warmack and the undersigned inspector on the field portion of this inspection. Both Mr. Barnum and Mr. Steve Tanner were present during the closeout session.

1. PERMITS:

A follow-up on federal NOV 88-2-116-2 revealed that in addition to a submittal made July 8, 1988, a submittal of drawings and certifications was also made on August 5, 1988. The Division has reviewed them, and on August 23, 1988 issued a conditional approval of the drawings and certifications of the haul roads and sediment ponds.

4c. SEDIMENT PONDS:

At the time of this inspection, the mine water pond 005 was discharging and a sample was gathered for analysis.

A survey of the sediment ponds was just completed August 24, 1988. Upon compilation of the data and mapping of the ponds, sediment levels and whether or not ponds need to be cleaned can be determined.

4d. OTHER SEDIMENT CONTROL MEASURES:

Follow-up on TDN 88-02-107-8 revealed that the operator is currently mapping the location and size of all areas within the permit that do not drain to a sediment pond for inclusion to the MRP as small area exemptions. Two additional areas requiring small area exemptions have been identified since the issuance of the TDN. They are:

1. The area draining into Whiskey Creek which is just south of the mine loadout and fan.
2. The area just south of the Val-Cam loadout which contains the vegetation test plot and small equipment bone yard.

Plans and maps of the areas will be submitted by the October 7 deadline.

There are several locations around the mine where new straw bales have been installed for sediment control.

INSPECTION REPORT  
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION Aug. 25, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

8. NONCOAL WASTE:

The pad area near the mine shop appears to have had oil spilled on it while lubricating some of the mine equipment. UMC 817.89 was brought to the operator's attention who committed to have the area cleaned up. Greater care will be exercised while lubricating equipment.

Copy of this Report:

Mailed to: Barry Barnum, Valley Camp

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: Daron R. Haddock #28 Date: Aug. 26, 1988