



Norman H. Bangertor

Governor

Dee C. Hansen

Executive Director

Dianne R. Nielson, Ph.D.

Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple

3 Triad Center, Suite 350

Salt Lake City, Utah 84180-1203

801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Dec. 13, 198910:00 a.m. to 12:00 noon

Permittee and/or Operators Name: VALLEY CAMP OF UTAH
 Business Address: SCOFIELD ROUTE HELPER, UTAH 84526
 Mine Name: BELINA COMPLEX Permit Number: ACT/007/001
 Type of Mining Activity: Underground XX Surface Other _____
 County: CARBON State: UTAH
 Company Official(s): STEVE TANNER
 State Official(s): DARON HADDOCK
 Partial: X Complete: _____ Date of Last Inspection: NOV. 28, 1989
 Weather Conditions: SUNNY, COLD
 Acreage: Permitted 3136 Disturbed 79 Regraded _____ Seeded _____ Bonded 79
 Enforcement Action: NONE

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION Dec. 13, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Upon the suggestion of Mr. Steve Tanner, the operators contracted maintenance representative, Jack Otani Jr., accompanied the undersigned inspector on this inspection. Maintenance items were discussed. No violations were apparent.

3. TOPSOIL:

The pile of vegetation supportive material along the railroad tracks at the ValCam Loadout, has been seeded. The pile appears to be stable.

4b. DIVERSIONS:

Most ditches and culverts are covered with snow. No drainage problems are apparent.

The small storage pad at the extreme south end of the ValCam Loadout was inspected. In the past, there was some question regarding treatment of drainage from this site. A new culvert has now been installed which will insure that drainage from this site reaches the sediment pond.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

All of the mine ponds and load out ponds were checked and found to be in good condition. Storage volumes are adequate in all ponds.

Pond #5 (mine discharge pond) was not discharging during the inspection.

4d. OTHER SEDIMENT CONTROL MEASURES:

A crew was working on snow removal along the haul road to the mine. Snow is being stored on pad areas above pond #4 to insure that all drainage from snow melt will report to the pond.

Near the oil storage shed, some steel beams have been pushed onto a berm. Although not a problem at this time, the operator will have the steel removed so as not to affect drainage pattern in the future.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION Dec. 13, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

18. SUPPORT FACILITIES:

The operation is currently stockpiling alot of coal on the ground at both the mine and the ValCam Loadout in preparation for some large shipments to be made in January. At the present time, storage appears to be taking place in designated storage areas.

Copy of this Report:

Mailed to: Steve Tanner - Valley Camp of Utah

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Daron R. Haddock

Inspectors Signature and Number: Daron R. Haddock #28 Date: Dec. 13, 1989