

### Document Information Form

Mine Number: C007001

File Name: Internal

To: DOGM

**From:**

Person N/A

Company Valley Camp of Utah

Date Sent: N/A

**Explanation:**

Inspection Report

\_\_\_\_\_  
\_\_\_\_\_

**cc:**

File in: C/007, 001, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date N/A For additional information



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

19K

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: FEB. 13, 1990  
9:15 A.M. to 10:45 A.M.

Permittee and/or Operators Name: VALLEY CAMP OF UTAH  
Business Address: SCOFIELD ROUTE HELPER, UTAH 84526  
Mine Name: BELINA COMPLEX Permit Number: ACT/007/001  
Type of Mining Activity: Underground  Surface  Other   
County: CARBON State: UTAH  
Company Official(s): ED FOUST  
State Official(s): DARON HADDOCK  
Partial:  Complete:  Date of Last Inspection: JAN. 11, 1990  
Weather Conditions: CLOUDY, LIGHT SNOW  
Acreage: Permitted 3136 Disturbed 79 Regraded      Seeded      Bonded 79  
Enforcement Action: NONE

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( X )	( )	( )	( X )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES	( )	( )	( )	( )
UTILITY INSTALLATIONS	( )	( )	( )	( )

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0003 Date N/A

In C/007, 001, Internal

For additional information



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: FEB. 13, 1990  
9:15 A.M. to 10:45 A.M.

Permittee and/or Operators Name: VALLEY CAMP OF UTAH  
Business Address: SCOFIELD ROUTE HELPER, UTAH 84526  
Mine Name: BELINA COMPLEX Permit Number: ACT/007/001  
Type of Mining Activity: Underground  Surface  Other   
County: CARBON State: UTAH  
Company Official(s): ED FOUST  
State Official(s): DARON HADDOCK  
Partial:  Complete:  Date of Last Inspection: JAN. 11, 1990  
Weather Conditions: CLOUDY, LIGHT SNOW  
Acreage: Permitted 3136 Disturbed 79 Regraded      Seeded      Bonded 79  
Enforcement Action: NONE

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( X )	( )	( )	( X )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( X )	( )	( )	( X )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION FEB. 13, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

The mine site received approximately twelve inches of new snow overnight with snow continuing to fall. About three feet of snow now covers most of the mine site and load out facility.

Diversions are all covered with snow and their effectiveness is difficult to determine. No surface drainage was leaving the site.

Sediment ponds appear to be in good condition with adequate storage volume available.

15. CESSATION OF OPERATIONS:

The mine and the load out facility were not in operation during the inspection. The mine has shut down temporarily due to coal shipping problems. Coal is currently stockpiled in the permitted storage areas and there is little room for additional coal.

The mine plans to be idle the remainder of this week, but may start up again the first of next week.

16. ROAD MAINTENANCE:


There is little traffic using the roads. Maintenance consists of snow removal.

Copy of this Report:

Mailed to: Ed Foust, Valley Camp of Utah

Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)

Filed to: PFO



Inspectors Signature and Number: Daron R. Haddock #28 Date: Feb. 13, 1990