

Document Information Form

Mine Number: C/007/001

File Name: Internal

To: DOGM

From:

Person N/A

Company Valley Camp of Utah

Date Sent: N/A

Explanation:

Inspection Report

cc:

File in: C/007/001, 1991, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

0021
JH

INSPECTION REPORT

INSPECTION DATE & TIME: March 20, 1991; 3:30 p.m. to 6:00 p.m.

Permittee and/or Operators Name: Valley Camp of Utah, Inc.
Business Address: Scotfield Route, Helper, Utah 84526
Mine Name: Belina Complex Permit Number: ACT/007/001
Type of Mining Activity: Underground X Surface Other
County: Carbon Company Official (s): Steven Tanner
State Official(s): Rick Summers, Randy Harden
Partial: x Complete: Date of Last Inspection: x/x/91
Weather Conditions: overcast, light snow, heavy snow last p.m.
Acreage: Permitted 3136 Disturbed 79 Regraded Seeded Bonded 79
Enforcement Action: none.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES	()	()	()	()
UTILITY INSTALLATIONS	()	()	()	()

File in:

Refer to Record No 0001 Date
In C/007/001, 1991, Internal
For additional information



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

DQZ
[Signature]

INSPECTION REPORT

INSPECTION DATE & TIME: March 20, 1991; 3:30 p.m. to 6:00 p.m.

Permittee and/or Operators Name: Valley Camp of Utah, Inc.
Business Address: Scotfield Route, Helper, Utah 84526
Mine Name: Belina Complex Permit Number: ACT/007/001
Type of Mining Activity: Underground Surface Other
County: Carbon Company Official (s): Steven Tanner
State Official(s): Rick Summers, Randy Harden
Partial: Complete: Date of Last Inspection: x/x/91
Weather Conditions: overcast, light snow, heavy snow last p.m.
Acreage: Permitted 3136 Disturbed 79 Regraded Seeded Bonded 79
Enforcement Action: none.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	(X)
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES	()	()	()	()
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION: 3/20/91

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

At the time of the inspection, a snow storm the previous evening had covered the site with approximately 4-6 inches of snow. The inspection consisted of an opening office visit and inspection of pond reports and records and a site tour of the mine site facilities. The loadout site was not inspected. The recent snow made the inspection difficult as the diversions, pads, culverts, etc. were covered with snow. One diversion was flowing from melt from the haul road. The diversion was functioning well and the drop inlet to the pond was clear and functional.

c. SEDIMENT PONDS AND IMPOUNDMENTS:

Pond inspections for the quarter were done on March 13, 1991. The report noted the embankments were covered with snow. No problems were noted.

f. EFFLUENT LIMITATIONS:


NPDES self-monitoring reports were current for the month of February. No discharges were noted with the exception of point 005A (mine water to Whiskey Creek). The Division has received copies of the report and they are on file in the Division offices.

Copy of this Report:

Mailed to: Steve Tanner (Valley Camp) and Brian Smith (OSM-AFO)

Given to: Daron Haddock and Joe Helfrich - DOGM

Inspectors Signature and Number:

#15  Date: 3/29/91