

### Document Information Form

Mine Number: C/007/001

File Name: Internal

To: DOGM

From:  
Person N/A

Company Valley Camp of Utah Inc

Date Sent: N/A

Explanation: INSPECTION REPORT.

cc:

File in: C/007/001, 1991, Internal

- Refer to:
- Confidential
  - Shelf
  - Expandable

Date \_\_\_\_\_ For additional information



OK 27

inspection report

Permit No. ACT/007/001  
Inspection Date October 29, 1991

Permittee/Operator Name Valley Camp of Utah  
Business Address Scofield Route  
City Helper State Utah Zip 84526  
Mine Belina Complex  Surface  Underground  Other  
County Carbon State Utah  
Company Official(s) Steve Tanner  
State Official(s) Stephen J. Demczak  
Time of inspection 8:00  a.m.  p.m. to 3:00  a.m.  p.m.  Partial  Complete  
Date of last inspection September 4, 5, 1991 Weather conditions Cool, 10" snow  
Acreage 3136  Permitted 79  Disturbed 0  Regraded 0  Seeded 79  Bonded  
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	11. Contemporaneous reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Stream channel diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	14. Subsidence control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15. Cessation of operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	- Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities installations				

WHITE - DOGM    YELLOW - OSM    PINK - PERMITTEE/OPERATOR    GOLDENROD - NOV FILE

DOGM/IR-1

an equal oppor

- File in:
- Confidential
  - Shelf
  - Expandable

Refer to Record No 0002 Date N/A  
In C1007/001, 1991, Internal  
For additional information



Permit No. ACT/007/001  
Inspection Date October 29, 1991

inspection report

Permittee/Operator Name Valley Camp of Utah  
Business Address Scotfield Route  
City Helper State Utah Zip 84526  
Mine Belina Complex  Surface  Underground  Other  
County Carbon State Utah  
Company Official(s) Steve Tanner  
State Official(s) Stephen J. Demczak  
Time of inspection 8:00  a.m.  p.m. to 3:00  a.m.  p.m.  Partial  Complete  
Date of last inspection September 4, 5, 1991 Weather conditions Cool, 10" snow  
Acreage 3136  Permitted 79  Disturbed 0  Regraded 0  Seeded 79  Bonded  
Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	10. Slides and other damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	11. Contemporaneous reclamation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Stream channel diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	14. Subsidence control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15. Cessation of operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Other sediment control measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
- Surface and groundwater monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
- Effluent limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	- Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	17. Other transportation facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**INSPECTION REPORT COMMENTS**

Permit No. ACT/007/001

Inspection Date October 29, 1991

Please number comments to correspond with topics on previous page.

1. Permits -

- a. The bond for Valley Camp is \$2.3 million by Federal Insurance Co.
- b. The insurance is by Home Indemnity Co. with policy number GL 99-43.43 and is self renewing.
- c. NPDES - UT0022985 and September, 1991 sampling was viewed. The only discharge was 005A for mine discharge. The average discharge was 258 mg/l and the limit is set at 700 mg/l. This is well within the allowable limit.
- d. Water sampling was taken for 3rd quarter and is being finalized.
- e. The pedestrian survey was taken in mid October, 1991 and is presently being complied.
- f. Valley Camp is presently crossing an underground dike for access for future reserves.
- g. Valley Camp has temporary approval for storage of cap and powder magazines. Copy of approval is enclosed.

3. Topsoil -

The topsoil piles were inspected and showed no signs of erosion or breach of berms built by straw bales.

4b. Diversions -

The diversions were snow covered and no runoff was apparent. The diversions

Copy of report mailed to \_\_\_\_\_

Copy of report given to \_\_\_\_\_

Inspector's signature  No. \_\_\_\_\_

WHITE - DOGM    YELLOW - OSM    PINK - PERMITEE/OPERATOR    GOLDENROD - NOV FILE

**INSPECTION REPORT COMMENTS**

Permit No. ACT/007/001

Inspection Date October 29, 1991

Please number comments to correspond with topics on previous page.

were cleaned up earlier due to the late summer rain storms.

4c. Sediment Ponds and Impoundments -

At the time of inspection no ponds were discharging. Ponds were covered with snow. No apparent problems were noted. Pond 004A will be cleaned out next year.

5. Explosives -

Approval for temporary cap and powder magazine storage was given by the Division as of October 16, 1991. Enclosed is a copy of the letter.

Copy of report mailed to Valley Camp, OSM/Brian Smith, DOGM/Joe Helfrich

Copy of report <sup>filed</sup> ~~given~~ to PFO

Inspector's signature  Stephen J. Demczak No. 39

WHITE - DOGM YELLOW - OSM PINK - PERMITTEE/OPERATOR GOLDENROD - NOV FILE