

7010



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION DATE & TIME: 5/20/92
1:00 p.m. to 3:30 p.m.

Permittee and/or Operator's Name: Valley Camp of Ut.
Business Address: Scofield Route Helper, Utah 84526
Mine Name: BELINA COMPLEX Mine Permit Number: ACT/007/001
Type of Mining Activity: Underground x Surface Other
County: Carbon Company Official(s): Steve Tanner
State Officials(s): Sharon Falvey, Wayne Western
Federal Official(s): None
Partial: x Complete: Date of last Inspection: April 29, 1992
Weather Conditions: Cloudy, Light Rain
Acreage: Permitted-3136 Disturbed-79 Regraded-0 Seeded-0
Bonded-79 Enforcement Action: no

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(x)	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(x)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(x)	()	()	(x)
d. OTHER SEDIMENT CONTROL MEASURES	(x)	()	()	(x)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	(x)	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	(x)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION: 5/21/92

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

c. SEDIMENT PONDS AND IMPOUNDMENTS

Although there were recent rain events the pond was not discharging during my visit. A portion of the pond surface was covered with an oil sheen. The pond is equipped with an oil skimmer.

d. OTHER SEDIMENT CONTROL MEASURES

New straw bales were replaced throughout the site.

16. ROADS

b. DRAINAGE CONTROLS

The operator had placed the vinyl elephant trunks along the steep culvert outlets of road drainage. Water was flowing through the trunks at the time of my inspection. The trunks were functioning properly.

Copy of this Report:

Mailed to: Valley Camp of Utah, Brian Smith (OSM)

Given to: Daron Haddock, Wayne Western, Joe Helfrich (DOGM)

Inspector's Signature: Sharon Falvey

#38 Date: 5/28/92