

*Handwritten initials/signature*



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial: XX Complete:      Exploration     

Inspection Date/Time: March 31, 1993/9:00am-11:00am

Date of Last Inspection: February 17, 1993

Mine Name: Belina Complex County: Carbon Permit Number: ACT/007/001  
Permittee and/or Operator's Name: Valley Camp of Utah  
Business Address: Scofield Route, Helper, UT 84526  
Type of Mining Activity: Underground XX Surface      Prep. Plant      Other       
Officials(s): State: Stephen J. Demczak Company: Ed Foust  
Federal Official(s):      Weather Conditions: 30's Snow 12"  
Existing Acreage: Permitted-3136 Disturbed-79 Regraded-     Seeded-     Bonded-79  
Increased/Decreased: Permitted-     Disturbed-     Regraded-     Seeded-     Bonded-      
Status:      Exploration/ X Active/      Inactive/      Temp Cessation/      Bond Forfeiture  
Reclamation (      Phase I/      Phase II/      Final Bond Release/      Liability      Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[XX]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: March 31, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The snow on the mine site still prevented the access of all diversions on the property. The two main diversions which could be seen was out of compliance, thus a Notice of Violation was issued (93-39-1-1). These diversions located at the loadout and the main haul road to the mine were filled with sediment or rocks, which either hindered or blocked the flow of water. The operator has the necessary equipment and manpower to abate this violation quickly.

4b. Sediment Ponds and Impoundments -

All ponds were still snow covered, therefore erosion of inlets, outlets or slopes could not be seen. The ponds were not discharging, but the mine pond was only inches from discharging. If the snow melts quickly, this mine pond could discharge.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah, Ed Foust  
Mailed to: Bernie Freeman (OSM)  
Given to: Joe Helfrich (DOGM)  
Filed to: Price Field Office  
Date: April 6, 1993

Inspector's Signature and Number:  39  
Stephen J. Demczak