



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

John 7

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Partial: XX Complete: Exploration
Inspection Date/Time: June 17, 1993/08:30am-12:00pm
Date of Last Inspection: May 13, 1993

Mine Name: Belina Complex County: Carbon Permit Number: ACT/007/001
Permittee and/or Operator's Name: Valley Camp of Utah
Business Address: Scofield Route, Helper, UT 84526
Type of Mining Activity: Underground XX Surface Prep. Plant Other
Officials(s): State: Stephen J. Demczak Company: Steve Tanner
Federal Official(s): Weather Conditions: Raining 50's
Existing Acreage: Permitted-3136 Disturbed-79 Regraded Seeded Bonded-79
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded
Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

EVALUATED N/A COMMENTS NOV/ENF

Table with 4 columns: Item, Evaluated, N/A, Comments, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: June 17, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4b. Sediment Ponds and Impoundments -

The sediment to the mine site was discharging and all other ponds were not. All ponds did contain a small amount of water. There was no signs of erosion from slopes or inlets and outlets of the ponds. Embankments appear to be stable.

10. Slides -

There are two small earth slides at the mine site located by the coal storage area. The slides will be repaired when the ground dries up and can be compacted.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah, Steve Tanner

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 23, 1993

Inspector's Signature and Number:


Stephen J. Demozak

#39