



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

Norman H. Bangertter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial:      Complete: XX Exploration     

Inspection Date/Time: October 14&15, 1993/08:00am-04:00pm

Date of Last Inspection: October 8, 1993

Mine Name: Belina Complex County: Carbon Permit Number: ACT/007/001  
Permittee and/or Operator's Name: Valley Camp of Utah  
Business Address: Scofield Route, Helper, UT 84526  
Type of Mining Activity: Underground XX Surface      Prep. Plant      Other       
Officials(s): State: Stephen J. Demczak Company: Gary Fritz  
Federal Official(s):      Weather Conditions: Cool 30's  
Existing Acreage: Permitted-3136 Disturbed-79 Regraded-     Seeded-     Bonded-79  
Increased/Decreased: Permitted-     Disturbed-     Regraded-     Seeded-     Bonded-      
Status:      Exploration/ X Active/      Inactive/      Temp Cessation/      Bond Forfeiture  
Reclamation (      Phase I/      Phase II/      Final Bond Release/      Liability      Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[XX]
2. SIGNS AND MARKERS	[XX]	[ ]	[ ]	[ ]
3. TOPSOIL	[XX]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[ ]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	[ ]	[XX]	[XX]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[XX]	[ ]
d. WATER MONITORING	[XX]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[XX]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[XX]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[XX]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[XX]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[XX]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[XX]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[XX]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[XX]	[ ]	[ ]	[ ]
13. REVEGETATION	[XX]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[XX]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[XX]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[XX]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[XX]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[XX]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[XX]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[XX]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[XX]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[XX]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: October 14&15, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

- a) The insurance policy (GLR9085595) has been updated to expire April 1, 1994. They have above the minimum requirements on each occurrence and aggregate.
- b) Reclamation agreement is by Home Indemnity Co. and the policy number is 8099-56-50 with a bond set at 2.3 million dollars to cover 79 acres of disturbed area. Permit area is 3738 acres.
- c) The permit expires on August 24, 1994. The current permit was viewed and was signed by both parties.
- d) The UNPDES permit sampling for May met all performance standards required on the permit.
- e) Reviewed the operators quarterly pond inspection with no discharge occurring for the third quarter of 1993.
- f) The AS-builts of the sediment ponds and filter ponds were inspected. The sediment pond drawings were adequate, but the filter pond designs on the size of pipes were missing from the drawing viewed. The filter pond AS-built drawing in the MRP was not labeled AS-built. A NOV was written N93-39-9-2-1 for not having complete designs.

4b. Sediment Ponds and Impoundments -

The sediment ponds 001A and 003A had erosion to the inlets to the pond. A NOV 93-39-2-2 was written for failure to maintain inlet to sediment pond and prevent erosion.

INSPECTION REPORT  
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: October 14&15, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4d. Water Monitoring -

The third quarter water monitoring samples were taken and second quarter was reviewed with all correct parameters taken.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah, Steve Tanner

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: November 2, 1993

Inspector's Signature and Number:

  
Stephen J. Demczak

#39