

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: November 9 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversion ditches were not breached and were not filled with sediment. Diversions were functioning as designed.

4b. Sediment Ponds and Impoundments -

Ponds were inspected and violation of pond 001A & 003A were terminated. No pond was discharging at the time of inspection.

4c. Other Sediment Control Measures -

The Valley Camp MRP has six ASCA areas which are identified. The sediment control measures vary from each ASCA. Some of the methods used in treatment is straw pits, depressions, natural vegetation, paved road, revegetation, riprap, rock gabion, sediment basin, straw bales, and silt fencing. The upper topsoil storage at the mine site also uses berms but is not mentioned in the ASCA portion of the MRP.

The R645-301-742.110 regulation states, "Appropriate sediment control measures will be designed, constructed and maintained using the best technology currently available to:"

742.111, "Prevent, to the extent possible, additional contributions of sediment to stream flow or to runoff outside the permit area;"

742.112, "Meet the effluent limitations under R645-301-751; and

742.113, "Minimize erosion to the extent possible."

The current MRP does not completely describe by design the alternative sediment control area. The designs should be adequate enough to replace any sediment control measures that are destroyed by wildlife, silted-up, or deteriorated by the environment. In which, any person could read the plan and install the sediment control measure which would resemble and be located as the pre-existing installation.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: November 19, 1993

Inspector's Signature and Number:


Stephen J. Demczak

#39