



UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

### VACATION/TERMINATION OF NOTICE OF VIOLATION/CESSATION ORDER

To the following Permittee or Operator:

Name Valley Camp of Utah, Inc.

Mailing Address Scofield Route, Helper, UT 84526

State Permit No. ACT/007/001

Utah Coal Mining & Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated* (1953):

Notice of Violation No. N 93-39-9-2 dated October 22, 1993, 19 93

Cessation Order No. C \_\_\_\_\_ dated \_\_\_\_\_, 19 \_\_\_\_\_

Part 1 of 2 is  vacated  terminated because plans were submitted.

(Finished October 15, 1993) (Good Faith Points)

Part 2 of 2 is  vacated  terminated because inlets to pond was repaired.

(Finished October 15, 1993) (Good Faith Points)

Part \_\_\_\_\_ of \_\_\_\_\_ is  vacated  terminated because \_\_\_\_\_

Date of service/ mailing November 10, 1993

Time of service/ mailing 12:00  a.m.  p.m.

James L. Littman

Permittee/Operator representative

Vice Chairman & CEO

Title

Signature

Stephen J. Demczak

Division of Oil, Gas & Mining

Reclamation Specialist

Title

Signature



NO. N 93-30-9-2

notice of violation

To the following Permittee or Operator:

Name Valley Camp of Utah, Inc.

Mine Belina Complex  Surface  Underground  Other

County Carbon State Utah Telephone 801-448-9413

Mailing Address Scofield Route, Helper, UT 84526

State Permit No. ACT/007/001

Ownership Category  State  Federal  Fee  Mixed

Date of inspection 10/14 & 15/93, 1993

Time of inspection 8:30  a.m.  p.m. to 4:00  a.m.  p.m.

Operator Name (other than Permittee) \_\_\_\_\_

Mailing Address \_\_\_\_\_

Under authority of the Utah Coal Mining and Reclamation Act, Section 40-10-1 et seq., *Utah Code Annotated*, 1953, the undersigned authorized representative of the Division of Oil, Gas & Mining has conducted an inspection of above mine on above date and has found violation(s) of the act, regulations or required permit condition(s) listed in attachment(s). This notice constitutes a separate Notice of Violation for each violation listed.

You must abate each of these violations within the designated abatement time. You are responsible for doing all work in a safe and workmanlike manner.

The undersigned representative finds that **cessation of mining is**  **is not**  expressly or in practical effect required by this notice. For this purpose, "mining" means extracting coal from the earth or a waste pile, and transporting it within or from the mine site.

This notice shall remain in effect until it expires as provided on reverse side of this form, or is modified, terminated or vacated by written notice of an authorized representative of the director of the Division of Oil, Gas & Mining. Time for abatement may be extended by authorized representative for good cause, if a request is made within a reasonable time before the end of abatement period.

CERTIFIED MAIL #AP 734 906 862\*\*

Date of service/mailling October 22, 1993

Time of service/mailling 12:00  a.m.  p.m.

Permittee/Operator representative \_\_\_\_\_

Title \_\_\_\_\_

Signature \_\_\_\_\_

Stephen J. Demczak

Reclamation Specialist

Division of Oil, Gas & Mining representative \_\_\_\_\_

Title \_\_\_\_\_

Signature Stephen J. Demczak

Identification Number #39

SEE REVERSE SIDE

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE



**NOTICE OF VIOLATION NO. N 93-39-9-2**

B4

Violation No. 1 of 2

Nature of violation

Failure to have complete designs and drawings of filter pond (005A). The diameter of pipe used in pond are not shown or found in text during the inspection.

Provisions of act, regulations or permit violated

R645-301-533.700

R645-301-733.100

~~R645-512-240~~

R645-301-512-240

Portion of operation to which notice applies

Filter Pond (005A)

Remedial action required (including any interim steps)

Submit a complete design drawing of pond (005A) and also an as built drawing.

Abatement time (including interim steps)

November 10, 1993 at 8:00a.m.



B10

NOTICE OF VIOLATION NO. N 93-99-9-2

Violation No. 2 of 2

Nature of violation

Failure to maintain the inlets to pond of 001A and 003A (sediment ponds).

Inlets to sediment ponds are eroded.

Provisions of act, regulations or permit violated

R645-301-742.211.3

R645-301-742.110

Portion of operation to which notice applies

Sediment ponds 001A and 003A.

Remedial action required (including any interim steps)

Repair inlets to comply with R645-301-742.211.3 and R645-301-742.110

Abatement time (including interim steps)

October 29, 1993 at 8:00a.m.