

0005

Document Information Form

Mine Number: C/007/001

File Name: Internal

To: DOGM

From:

Person N/A

Company Dept. of Natural Resources
Division of Oil, Gas and Mining.

Date Sent: 03/17/1994

Explanation:

Inspection Report.

cc:

File in: C/007,001, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: XX Complete: Exploration

Inspection Date/Time: March 17, 1994/09:30am-02:30pm

Date of Last Inspection: February 20, 1994

Mine Name: Belina Complex County: Carbon Permit Number: ACT/007/001
Permittee and/or Operator's Name: Valley Camp of Utah
Business Address: Scofield Route, Helper, UT 84526
Type of Mining Activity: Underground XX Surface Prep. Plant Other
Officials(s): State: Stephen J. Demczak Company: Steve Tanner
Federal Official(s): Weather Conditions: cool, 20's
Existing Acreage: Permitted-3136 Disturbed-79 Regraded- Seeded- Bonded-79
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ X Active/ Inactive/ Temp Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
 - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NDV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[]	[XX]	[]
2. SIGNS AND MARKERS	[XX]	[]	[XX]	[]
3. TOPSOIL	[]	[]	[]	[]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[]	[]	[]	[]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[]	[]	[]	[]
c. OTHER SEDIMENT CONTROL MEASURES	[]	[]	[]	[]
d. WATER MONITORING	[]	[]	[]	[]
e. EFFLUENT LIMITATIONS	[]	[]	[]	[]
5. EXPLOSIVES	[]	[]	[]	[]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[]	[]	[]	[]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[]	[]	[]	[]
8. NONCOAL WASTE	[]	[]	[]	[]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[]	[]	[]	[]
10. SLIDES AND OTHER DAMAGE	[]	[]	[]	[]
11. CONTEMPORANEOUS RECLAMATION	[]	[]	[]	[]
12. BACKFILLING AND GRADING	[]	[]	[]	[]
13. REVEGETATION	[]	[]	[]	[]
14. SUBSIDENCE CONTROL	[]	[]	[]	[]
15. CESSATION OF OPERATIONS	[]	[]	[]	[]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[]	[]	[]	[]
b. DRAINAGE CONTROLS	[XX]	[]	[]	[]
17. OTHER TRANSPORTATION FACILITIES	[]	[]	[]	[]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[]	[]	[]	[]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[]	[]	[]	[]
20. AIR QUALITY PERMIT	[]	[]	[]	[]
21. BONDING & INSURANCE	[]	[]	[]	[]

Date 3-17-94

File in: Confidential Shelf Expandable
Refer to Record No. 0001 In C/007-001, 1994, Internal
For additional information

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001 DATE OF INSPECTION: March 17, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The Mining and Reclamation Plan was reviewed in regard to snow removal on the haulage road to the mine. The reason for review was the outslope of the road had blackened snow which is next to Eccles Creek. The plan does not address the removal of snow but does address water runoff using ditches and culverts in a controlled manner.

The snow melt could be seen entering into Eccles Creek. Since the snow was dark in color, water quality became a concern; thus, water samples were taken. Samples were taken above and below the permit area and within. At this time, an NOV has not been issued.

2. Signs and Markers -

Both the operators and the permit holders identification signs were inspected. The operator's identification sign meets all the requirements of the regulations. The permit holder's identification sign (Valley Camp) lacks several requirements. A guideline has been requested on identification signs and, as of this date, no guidelines have been forwarded to the Price Field Office.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Valley Camp of Utah


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: April 8, 1994

Inspector's Signature and Number:


Stephen J. Demczak

#39