



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

1594 West North Temple, Suite 1210
P.O. Box 145801
Salt Lake City, Utah 84114-5801
(801) 538-5340
(801) 359-3940 (Fax)

Partial: XXX Complete: Exploration:

Inspection Date & Time: 11/26/96 / 8:00a.m.-11:00a.m.

Date of Last Inspection: 10/7/96

Mine Name: White Oak #1 & #2 County: Carbon Permit Number: ACT/007/001
Permittee and/or Operator's Name: White Oak Mining and Construction Company
Business Address: Scofield Route, Helper, Utah 84526
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): John Walters
State Officials(s): Steve Demczak Federal Official(s): None
Weather Conditions: Cool, 20's
Existing Acreage: Permitted- 3136 Disturbed- 79 Regraded- 0 Seeded- 0 Bonded- 79
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows list 21 inspection items with checkboxes and some pre-filled 'XX' marks.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/001

DATE OF INSPECTION: 11/26/96

(Comments are Numbered to Correspond with Topics Listed Above)

4A. DIVERSIONS -

The diversions were spot-checked and were functioning as designed. Some of the diversions were flowing water to the sediment ponds.

4B. SEDIMENT PONDS -

The sediment pond at the mine site is scheduled to be cleaned out in early December. The permittee is going to scoop out the sediment within the pond. The material is going to be stored and dried on the pad area by the coal pile. Once dried it will be blended with the coal and sold. The permittee has been advised to survey the pond after clean out.

8. NONCOAL WASTE -

There were several empty oil cans at the coal loadout at the mine site. The permittee removed the cans and put them into a noncoal waste storage area. The rest of the property was cleared of noncoal waste.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: John Walters (White Oak)

Marcia Petta (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: December 3, 1996

Inspector's Signature: _____

Stephen J. Demczak

#39