

**From:** Thomas W Lloyd <twlloyd@fs.fed.us>  
**To:** "Pam Grubaugh-Littig" <PAMGRUBAUGHLITTIG@utah.gov>,  
<PAMGRUBAUGHLITTIG@utah.gov>  
**Date:** 7/30/2004 10:48:37 AM  
**Subject:** Re: Boardinghouse Subsidence inspection.

Pam,  
Attached is a photo of the site. I would send more but the photos max my computer limit for email.

Tom

(See attached file: DCP\_1109.JPG)[

"Pam  
Grubaugh-Littig"  
<PAMGRUBAUGHLITTI  
G@utah.gov> To  
<creed01@fs.fed.us>,  
<mnyman@fs.fed.us>,  
07/29/2004 08:54 AM <twlloyd@fs.fed.us>, "Pete Hess"  
<PETEHESS@utah.gov>  
cc  
  
Subject  
Re: Boardinghouse Subsidence  
inspection.

Tom, thank you so much for the update.

>>> Thomas W Lloyd <twlloyd@fs.fed.us> 07/28/04 05:11PM >>>

Today, Pete Hess and I inspected the subsidence area just inside the FS

boundry in Boardinghouse Canyon. The vegetations is doing very well with native grasses 2 to 3 feet tall as well other natives species. There is aspen regeneration occurring as well. The ground appears to have sabilized as a result of the back filling that was done 2 years ago.

Pete and I removed the fence.

We will plan to return to the area next year for a follow-up inspection.

Tom Lloyd

