



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Representatives Present During the Inspection:
OGM Karl Houskeeper Environmental Scientist III

Inspection Report

Permit Number: C0070001
Inspection Type: PARTIAL
Inspection Date: Tuesday, January 30, 2007
Start Date/Time: 1/30/2007 9:00:00 AM
End Date/Time: 1/30/2007 11:00:00 AM
Last Inspection: Thursday, December 14, 2006

Inspector: Karl Houskeeper, Environmental Scientist III
Weather: Clear, Temp. 20 Deg. F.
InspectionID Report Number: 1204

Accepted by: whedberg
2/5/2007

Permittee: **LODESTAR ENERGY INC**
Operator: **LODESTAR ENERGY INC**
Site: **WHITE OAK MINE**
Address: **2525 HARRODSBURG RD STE 235, LEXINGTON KY 40504-1628**
County: **CARBON**
Permit Type: **PERMANENT COAL PROGRAM**
Permit Status: **RECLAIMED**

Current Acreages

| | |
|----------|------------------------|
| 3,906.00 | Total Permitted |
| 151.10 | Total Disturbed |
| | Phase I |
| | Phase II |
| | Phase III |

Mineral Ownership

- Federal
- State
- County
- Fee
- Other

Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Outstanding Violations: OSM- C04-140-116-001, DOGM- FTA C03-39-1-1, FTA C03-42-1-1, C03-42-1-2, FTA C03-42-1-3, C0-51--1-1, C03-50-2-1, FTA C04-39-1-1, C03-39-1-1, C03-42-1-2, C03-42-1-1, C03-42-1-3, C03-51-1-1, N03-46-1-1, and N03-50-1-1. These violations received an "Exclusionary Code" in the AVS on October 21, 2004 due to the General Settlement Agreement signed on August 18, 2004. The Rennert parties, Congress Financial, Wexford and the Debtors trustee will receive the "exclusion" code. Lodestar Energy, Inc will remain liable in the AVS.

There has been some grazing on the site, as reported by the AMR program. The owner of the grazing allotment is Warren Bailey.

Inspector's Signature:

Date Wednesday, January 31, 2007

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0070001
 Inspection Type: PARTIAL
 Inspection Date: Tuesday, January 30, 2007

Inspection Continuation Sheet

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | Evaluated | Not Applicable | Comment | Enforcement |
|------------------------------------------------------------------|-------------------------------------|--------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and Markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Noncoal Waste | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Backfilling And Grading | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Cessation of Operations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17. Other Transportation Facilities | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS Check | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20. Air Quality Permit | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21. Bonding and Insurance | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 22. Other | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

1. Permits, Change, Transfer, Renewal, Sale

The road to the mine site was covered with snow. The snow is at the top of the gate.

2. Signs and Markers

No identification signs are at the main gate to the loadout or mine site.

22. Other

The Division issued the Determination to Forfeit at the White Oak Mine on May 1, 2003. Chapter 7 was filed by Lodestar Energy, Inc. on July 15, 2003. The Division negotiated with the Bankruptcy Trustee and Frontier Insurance to stabilize this site. The amount of \$999,000 was escrowed from Frontier Insurance Company on October 3, 2003. Ledcor (the Frontier contractor) started work at the White Oak Mine on October 13, 2003. Ledcor (the contractor for Frontier) left the site for the winter on December 17, 2003. Reclamation work at the White Oak Loadout was done by the Mark Wayment group. \$1.217 million was received from the Global Settlement Agreement and the contractor VCM was awarded the contract to continue reclamation at the White Oak Mine. Work started on October 3, 2004 and ended in December 2004. Reclamation work began in June 2005 and was completed on November 1, 2005 for the mine and November 4, 2005 for the loadout. Weed control was conducted by AMR during the summer of 2006.

On June 18, 2004, Lodestar trustee Bill Bishop filed the master settlement between various parties (including Renco and Wexford Capital) for reclamation in a "General Settlement Fund" outside of the Lodestar bankruptcy estate. Utah received \$1.217 million dollars - this was finalized by the Bankruptcy Court on August 18, 2004.

The contract with the Frontier contractor, Ledcor, was terminated in June 2004. The monies remaining from that contract were used for reclamation at White Oak.

AMR programs administered the reclamation work at the White Oak Mine and did additional reclamation at the loadout. All reclamation work is now completed. The Division will contract the spraying of weeds annually at the mine site for three years starting in 2006.