



0056

United States Department of the Interior
OFFICE OF SURFACE MINING
Reclamation and Enforcement
BROOKS TOWERS
1020 15TH STREET
DENVER, COLORADO 80202

(File) ACT/007/004

Copy to Joe

Jim

May 5, 1981

RECEIVED

MAY 7 1981

DIVISION OF
OIL, GAS & MINING

Mr. James W. Smith
Coordinator of Mined Land Development
Department of Natural Resources
1588 West North Temple
Salt Lake City, UT 84116

Dear Mr. Smith:

Enclosed please find a copy(s) of on-site inspection report. The inspection was conducted within MINES #3 & #4 during the period of April 28, 1981.

Price River Coal

If you have any questions or problems, please contact this office.

Sincerely,

Thomas E. Ehmett
Assistant Regional Director
Division of Inspection & Enforcement

REGION V ON-SITE INSPECTION REPORT

PRICE RIVER COAL COMPANY
MINES #3 & #4
P.O. Box 629
Helper, Utah 84526
(801) 472-3411

DATE: April 28, 1981
TIME: 1:45 p.m. - 2:30 p.m.
COUNTY AND STATE: Carbon County, Utah
COMPANY OFFICIAL: Robert Wiley
STATE OFFICIAL: Joe Helfrich
OSM OFFICIALS: Dave Schlick and Larry Damrau
STATE PERMIT NUMBER: ACT/007/004
NPDES PERMIT NUMBER: UT-0023086
MSHA ID NUMBER: 42-01202

GENERAL COMMENTS

A follow-up inspection was conducted to evaluate the remedial action taken by the company to abate Violation 1 of 1 of NOV 80-5-7-25, issued for failure to divert overland flow from undisturbed areas away from disturbed areas by means of temporary or permanent diversion structures.

Temporary control has been established by use of straw bales. Permanent control is scheduled to be established following the present UMWA strike. The violation is terminated.


D. L. DAMRAU
RECLAMATION SPECIALIST